

PAN AMERICAN SILVER CORP
Form 6-K
September 22, 2011
[Table of Contents](#)

SECURITIES AND EXCHANGE COMMISSION

Washington, D.C. 20549

FORM 6-K

Report of Foreign Private Issuer
Pursuant to Rule 13a-16 or 15d-16 of
the Securities Exchange Act of 1934

For the month of, September 2011

Commission File Number 000-13727

Pan American Silver Corp

(Translation of registrant's name into English)

1500-625 Howe Street, Vancouver BC Canada V6C 2T6

(Address of principal executive offices)

Indicate by check mark whether the registrant files or will file annual reports under cover of Form 20-F or Form 40F:

Form 20-F

Form 40-F

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Indicate by check mark if the registrant is submitting the Form 6-K in paper as permitted by Regulation S-T Rule 101(b)(1):

Indicate by check mark if the registrant is submitting the Form 6-K in paper as permitted by Regulation S-T Rule 101(b)(7):

Indicate by check mark whether by furnishing the information contained in this Form, the registrant is also thereby furnishing the information to the Commission pursuant to Rule 12g3-2(b) under the Securities Exchange Act of 1934.

Yes

No

If is marked, indicate below the file number assigned to the registrant in connection with Rule 12g3-2(b): 82-

Table of Contents

DOCUMENTS INCLUDED AS PART OF THIS REPORT

Document

- 1 Pan American Silver Corp. and Orko Silver Corp., La Preciosa Silver Property, Durango, México, Preliminary Economic Assessment Technical Report.

Table of Contents

Document 1

Table of Contents

Office Locations

Perth

87 Colin Street

West Perth WA 6005

PO Box 77

West Perth WA 6872

AUSTRALIA

Tel: +61 8 9213 9213

Fax: +61 8 9322 2576

ABN 99 085 319 562

perth@snowdengroup.com

Brisbane

Level 15, 300 Adelaide Street

Brisbane QLD 4000

PO Box 2207

Brisbane QLD 4001

AUSTRALIA

Tel: +61 7 3231 3800

Fax: +61 7 3211 9815

ABN 99 085 319 562

brisbane@snowdengroup.com

Vancouver

Suite 600

1090 West Pender Street

Vancouver BC V6E 2N7

CANADA

Tel: +1 604 683 7645

Fax: +1 604 683 7929

Reg No. 557150

vancouver@snowdengroup.com

Johannesburg

Technology House

Greenacres Office Park

Cnr. Victory and Rustenburg Roads

Victory Park

Johannesburg 2195

SOUTH AFRICA

PO Box 2613

Parklands 2121

SOUTH AFRICA

Tel: + 27 11 782 2379

Fax: + 27 11 782 2396

Reg No. 1998/023556/07

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

johannesburg@snowdengroup.com

London

Abbey House

Wellington Way

Weybridge

Surrey KT13 0TT, UK

Tel: + 44 (0) 1932 268 701

Fax: + 44 (0) 1932 268 702

london@snowdengroup.com

Belo Horizonte

Av. Afonso Pena 4121 / 302

Mangabeiras, 30130-009

Belo Horizonte MG Brazil

Tel: +55 (31) 3222-6286

Fax: +55 (31) 3222-6286

belohorizonte@snowdengroup.com

Website

www.snowdengroup.com

IMPORTANT NOTICE

This report was prepared in accordance with Form 43-101F1 Technical Report for Pan American Silver Corp. and Orko Silver Corp. This report is intended to be used by Pan American Silver Corp. and Orko Silver Corp. subject to the terms and conditions of Pan American Silver Corp's contract with Snowden Mining Industry Consultants Inc. That contract permits Pan American Silver Corp. and Orko Silver Corp. to file this report as a Technical Report with Canadian securities regulatory authorities pursuant to provincial securities legislation. Except for the purposes

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

legislated under provincial securities law, any other use of this report by any third party is at that party's sole risk.

Issued by: Vancouver Office

Doc Ref: 20110916 FINAL La Preciosa Technical Report.docx

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

1	<u>Summary</u>		14	
	<u>1.1</u>	<u>Property description and ownership</u>	14	
	<u>1.2</u>	<u>Geology and mineralisation</u>	14	
	<u>1.3</u>	<u>Status of exploration, development, and operations</u>	15	
	<u>1.4</u>	<u>Mineral resource estimate</u>	15	
	<u>1.5</u>	<u>Mining methods and Project infrastructure</u>	16	
	<u>1.6</u>	<u>Capital and operating costs and economic analyses</u>	17	
	<u>1.7</u>	<u>Mineral processing, metallurgical testing, and recovery methods</u>	19	
	<u>1.8</u>	<u>Environmental studies, permitting, and social and community impact</u>	19	
	<u>1.9</u>	<u>Conclusions and recommendations</u>	20	
	<u>1.10</u>	<u>Cautionary note regarding forward-looking information and statements</u>	21	
2	<u>Introduction</u>		23	
3	<u>Reliance on other experts</u>		26	
4	<u>Property description and location</u>		27	
	<u>4.1</u>	<u>Location, mineral tenure, and surface rights</u>	27	
	<u>4.2</u>	<u>Issuer's interest</u>	31	
	<u>4.3</u>	<u>Royalties, back-in rights, payments, agreements, and encumbrances</u>	31	
	<u>4.4</u>	<u>Environmental liabilities</u>	32	
	<u>4.5</u>	<u>Permits</u>	32	
	<u>4.6</u>	<u>Significant factors and risks</u>	32	
5	<u>Accessibility, climate, local resources, infrastructure and physiography</u>		33	
	<u>5.1</u>	<u>Access</u>	33	
	<u>5.2</u>	<u>Climate and length of operating season</u>	34	
	<u>5.3</u>	<u>Proximity to population centre and transport</u>	34	
	<u>5.4</u>	<u>Surface rights, land availability, infrastructure, and local resources</u>	34	
		<u>5.4.1</u>	<u>Surface rights, land availability, and mining areas</u>	34
		<u>5.4.2</u>	<u>Power, infrastructure, and water</u>	36
		<u>5.4.3</u>	<u>Local resources and mining personnel</u>	37
	<u>5.5</u>	<u>Topography, elevation, and vegetation</u>	39	
6	<u>History</u>		40	
	<u>6.1</u>	<u>Prior ownership, exploration, and development work</u>	40	
		<u>6.1.1</u>	<u>Late 19th century work</u>	40
		<u>6.1.2</u>	<u>Work by Luismin from 1981 to 1982 and 1994</u>	40
		<u>6.1.3</u>	<u>Work by Orko from 2003 to 2008</u>	41
7	<u>Geological setting and mineralisation</u>		43	
	<u>7.1</u>	<u>Regional geology</u>	43	

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

<u>7.2</u>	<u>Local geology</u>	45
<u>7.3</u>	<u>Property geology</u>	47
<u>7.4</u>	<u>Mineralisation</u>	49
8	<u>Deposit types</u>	52
9	<u>Exploration</u>	53
<u>9.1</u>	<u>Exploration by Luismin from 1981 to 1982 and 1994</u>	53
<u>9.2</u>	<u>Exploration by Orko from 2004 to 2008</u>	53
<u>9.3</u>	<u>Exploration by Pan American from 2009 to 2010</u>	54
10	<u>Drilling</u>	55
<u>10.1</u>	<u>Drilling summary and database</u>	55
<u>10.2</u>	<u>Drilling by Luismin from 1981 to 1982 and 1994</u>	58
<u>10.3</u>	<u>Drilling by Orko from 2005 to 2008</u>	58
<u>10.4</u>	<u>Drilling by Pan American from 2009 to 2010</u>	58
<u>10.5</u>	<u>Exploration targets</u>	59
<u>10.6</u>	<u>Material impact on accuracy and reliability of drilling results</u>	61
<u>10.7</u>	<u>Conclusions and recommendations</u>	62
11	<u>Sample preparation, analyses, and security</u>	63
<u>11.1</u>	<u>Sampling by Luismin from 1981 to 1982 and 1994</u>	63
<u>11.2</u>	<u>Sampling by Orko from 2005 to 2008</u>	63
	<u>11.2.1</u> <u>Sample preparation and security</u>	63
	<u>11.2.2</u> <u>Analytical methods</u>	64
	<u>11.2.3</u> <u>QAOC</u>	65
<u>11.3</u>	<u>Sampling by Pan American from 2009 to 2010</u>	76
	<u>11.3.1</u> <u>Sample preparation and security</u>	76
	<u>11.3.2</u> <u>Analytical methods</u>	77
	<u>11.3.3</u> <u>QAOC</u>	77
<u>11.4</u>	<u>Density measurements</u>	82
<u>11.5</u>	<u>Conclusions and recommendations</u>	83
12	<u>Data verification</u>	85
<u>12.1</u>	<u>Data verification by MDA and Pan American</u>	85
<u>12.2</u>	<u>Data verification by the current qualified persons</u>	85
	<u>12.2.1</u> <u>Site visit</u>	85
	<u>12.2.2</u> <u>Data reviews</u>	86
<u>12.3</u>	<u>Data adequacy</u>	87
13	<u>Mineral processing and metallurgical testing</u>	88
<u>13.1</u>	<u>Historical testing</u>	88
<u>13.2</u>	<u>Testing from 2007 and 2009</u>	88

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

	<u>13.2.1</u>	<u>Stage 1 flotation and agitation cyanidation tests</u>	88
	<u>13.2.2</u>	<u>Stage 2 bottle roll leaching tests</u>	92
	<u>13.2.3</u>	<u>Stage 3 cyanidation and flotation tests</u>	96
	<u>13.2.4</u>	<u>Mineralogical considerations</u>	101
	<u>13.2.5</u>	<u>Cyanidation</u>	102
	<u>13.2.6</u>	<u>Cyanide consumption</u>	102
<u>13.3</u>	<u>Testing from 2009 to 2010</u>		102
	<u>13.3.1</u>	<u>SGS test 18-09</u>	103
	<u>13.3.2</u>	<u>SGS test 18-10</u>	108
	<u>13.3.3</u>	<u>SGS test 40-10</u>	113
	<u>13.3.4</u>	<u>SGS test 60-10</u>	116
	<u>13.3.5</u>	<u>Summary of SGS test work</u>	118
<u>13.4</u>	<u>Sample representativity</u>		119
<u>13.5</u>	<u>Material issues and deleterious elements</u>		121
<u>13.6</u>	<u>Conclusions</u>		121
	<u>13.6.1</u>	<u>Metallurgical composites</u>	121
	<u>13.6.2</u>	<u>Gold and silver metallurgy</u>	122
	<u>13.6.3</u>	<u>Processing parameters</u>	124
	<u>13.6.4</u>	<u>Cyanide consumption</u>	124
	<u>13.6.5</u>	<u>Lime addition point</u>	125
<u>13.7</u>	<u>Recommendations</u>		125
	<u>13.7.1</u>	<u>Laboratory testing</u>	125
	<u>13.7.2</u>	<u>Sulphur data</u>	126
<u>14</u>	<u>Mineral resource estimates</u>		127
<u>14.1</u>	<u>Disclosure</u>		127
<u>14.2</u>	<u>Assumptions, methods and parameters 2010 mineral resource estimates</u>		127
<u>14.3</u>	<u>Supplied data, data preparation, data transformations, and data validation</u>		128
	<u>14.3.1</u>	<u>Supplied data</u>	128
	<u>14.3.2</u>	<u>Data preparation</u>	128
	<u>14.3.3</u>	<u>Data transformations</u>	129
	<u>14.3.4</u>	<u>Data validation</u>	130
<u>14.4</u>	<u>Geological interpretation, modeling, and domaining</u>		130
	<u>14.4.1</u>	<u>Geological interpretation and modelling</u>	130
	<u>14.4.2</u>	<u>Definition of grade estimation domains</u>	133
<u>14.5</u>	<u>Sample statistics</u>		133
	<u>14.5.1</u>	<u>Summary statistics</u>	133
	<u>14.5.2</u>	<u>Compositing of sample assay intervals</u>	135
	<u>14.5.3</u>	<u>Extreme grade value treatment</u>	137

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

<u>14.6</u>	<u>Variogram analysis and variogram modelling</u>	139
	<u>14.6.1</u> <u>Variography of veins</u>	139
	<u>14.6.2</u> <u>Variography of host rock</u>	141
<u>14.7</u>	<u>Estimation parameters</u>	144
	<u>14.7.1</u> <u>Block size selection</u>	144
	<u>14.7.2</u> <u>Estimation and sample search parameters</u>	144
	<u>14.7.3</u> <u>Grade interpolation and boundary conditions</u>	149
<u>14.8</u>	<u>Density</u>	150
<u>14.9</u>	<u>Estimation validation</u>	151
<u>14.10</u>	<u>Estimation post-processing</u>	153
<u>14.11</u>	<u>Comparison with previous estimates</u>	154
<u>14.12</u>	<u>Depletion for historical mining</u>	154
<u>14.13</u>	<u>Mineral resource classification</u>	155
<u>14.14</u>	<u>Mineral resource tabulation</u>	155
<u>14.15</u>	<u>Recommendations</u>	158
<u>15</u>	<u>Mineral reserve estimates</u>	160
<u>16</u>	<u>Mining methods</u>	161
<u>16.1</u>	<u>Geotechnical parameters</u>	161
	<u>16.1.1</u> <u>Data collection</u>	161
	<u>16.1.2</u> <u>Open pit mining parameters</u>	162
	<u>16.1.3</u> <u>Underground mining parameters</u>	162
<u>16.2</u>	<u>Dilution modelling and factors</u>	163
<u>16.3</u>	<u>Open pit mining</u>	165
	<u>16.3.1</u> <u>Pit optimisation</u>	165
	<u>16.3.2</u> <u>Pit design</u>	168
<u>16.4</u>	<u>Underground mining</u>	170
	<u>16.4.1</u> <u>Underground mining methods</u>	170
	<u>16.4.2</u> <u>Identification of production areas</u>	172
	<u>16.4.3</u> <u>Development and accesses</u>	173
<u>16.5</u>	<u>Mining schedule</u>	175
	<u>16.5.1</u> <u>Targets and methodology</u>	175
	<u>16.5.2</u> <u>Limits</u>	175
	<u>16.5.3</u> <u>Schedule</u>	176
<u>16.6</u>	<u>Waste rock dumps</u>	181
<u>16.7</u>	<u>Mining fleet</u>	182
<u>16.8</u>	<u>Workforce</u>	182
<u>16.9</u>	<u>Alternative mine concept</u>	182
<u>17</u>	<u>Recovery methods</u>	184

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

<u>18</u>	<u>Project infrastructure</u>		189
<u>18.1</u>	<u>Facility layout</u>		189
<u>18.2</u>	<u>Tailings facility</u>		189
<u>18.3</u>	<u>Transportation</u>		190
<u>18.4</u>	<u>Power</u>		191
<u>18.5</u>	<u>Water</u>		192
<u>19</u>	<u>Market studies and contracts</u>		194
<u>19.1</u>	<u>Marketing</u>		194
	<u>19.1.1</u>	<u>Product specification and selling costs</u>	194
	<u>19.1.2</u>	<u>Metal prices</u>	194
	<u>19.1.3</u>	<u>Assumptions</u>	194
<u>19.2</u>	<u>Contracts</u>		195
<u>20</u>	<u>Environmental studies, permitting, and social or community impact</u>		196
<u>20.1</u>	<u>Environmental summary</u>		196
<u>20.2</u>	<u>Expected material environmental issues</u>		197
<u>20.3</u>	<u>Waste and tailings disposal</u>		197
<u>20.4</u>	<u>Site monitoring</u>		197
<u>20.5</u>	<u>Water management</u>		198
<u>20.6</u>	<u>Permitting</u>		198
	<u>20.6.1</u>	<u>Applicable federal laws and regulations</u>	198
	<u>20.6.2</u>	<u>Applicable state laws and regulations</u>	199
	<u>20.6.3</u>	<u>Generally applicable Mexican standards</u>	199
<u>20.7</u>	<u>Social and community requirements</u>		199
<u>20.8</u>	<u>Project closure</u>		200
<u>21</u>	<u>Capital and operating costs</u>		201
<u>21.1</u>	<u>Capital costs</u>		201
	<u>21.1.1</u>	<u>Mining</u>	201
	<u>21.1.2</u>	<u>Processing and infrastructure</u>	201
	<u>21.1.3</u>	<u>Other initial capital</u>	202
	<u>21.1.4</u>	<u>Sustaining capital</u>	203
<u>21.2</u>	<u>Operating costs</u>		204
	<u>21.2.1</u>	<u>Mining</u>	205
	<u>21.2.2</u>	<u>Processing and general and administrative costs</u>	205
<u>22</u>	<u>Economic analysis</u>		207
<u>22.1</u>	<u>General</u>		207
<u>22.2</u>	<u>Taxes, royalties, levies, and interests</u>		208
	<u>22.2.1</u>	<u>Taxation</u>	208
	<u>22.2.2</u>	<u>Royalties</u>	208

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

<u>22.3</u>	<u>Economic model</u>	208
<u>22.4</u>	<u>Sensitivity analysis</u>	211
<u>23</u>	<u>Adjacent properties</u>	213
<u>24</u>	<u>Other relevant data and information</u>	214
<u>25</u>	<u>Interpretation and conclusions</u>	215
<u>25.1</u>	<u>Mineral resources</u>	215
<u>25.2</u>	<u>Mineral processing, metallurgical testing, and recovery methods</u>	216
<u>25.3</u>	<u>Mining and financial</u>	216
<u>25.4</u>	<u>Environmental and community</u>	217
<u>26</u>	<u>Recommendations</u>	218
<u>26.1</u>	<u>Project advancement</u>	218
<u>26.2</u>	<u>Mineral resources</u>	219
<u>26.3</u>	<u>Mineral processing, metallurgical testing, and recovery methods</u>	219
<u>26.4</u>	<u>Mining and financial</u>	220
<u>26.5</u>	<u>Environmental and community</u>	220
<u>27</u>	<u>References</u>	222
<u>28</u>	<u>Date, signatures, and certificates</u>	223

Tables

Table 1.1	La Preciosa Project mineral resource estimate effective 30 June 2011	16
Table 1.2	La Preciosa Project preliminary capital cost estimates	17
Table 1.3	La Preciosa Project preliminary operating cost estimates	18
Table 1.4	La Preciosa Project preliminary financial metric estimates(1)	18
Table 2.1	Responsibilities of each qualified person	24
Table 4.1	La Preciosa Property concession details	30
Table 5.1	Land owners in the area of proposed mine and plant facilities	35
Table 5.2	La Preciosa Project work force availability	38
Table 7.1	Vein volumes and orientations	51
Table 10.1	La Preciosa Property drillhole and channel database	55
Table 10.2	Downhole intersection results from exploration targets	60
Table 11.1	Summary of analytical techniques used to assay Orko s samples	64
Table 11.2	Details of the standards used by Orko	66
Table 11.3	Details of duplicate analyses of Orko drill core samples	73
Table 11.4	Details of the analytical techniques used to assay Pan American s samples	77

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 11.5	Details of the standards used by Pan American	79
Table 13.1	Metallurgy test results by Comision de Fomento Minero	88
Table 13.2	Details of the five 10 kg Orko metallurgical composites	89
Table 13.3	Rougher only flotation test results	90
Table 13.4	Rougher tailing screen assay data	90
Table 13.5	Orko cyanidation tests C1 to C3 results	91
Table 13.6	Screen assays of Orko test C3 leached residue	92
Table 13.7	Stage 2 agitation leaching composite summary data	94
Table 13.8	Stage 2 agitation leaching testwork results	95
Table 13.9	Details of composites used in PRA cyanidation tests C37 to C47	97
Table 13.10	PRA cyanidation test C37 to C42 results	97
Table 13.11	WMT flotation test W-09-02 results	99
Table 13.12	Rougher tailing screen assay data	99
Table 13.13	PRA cyanidation test C43 to C47 results	100
Table 13.14	Details of master composite used in SGS test 18-09	103
Table 13.15	Cyanidation tailing screen assay results	105
Table 13.16	Work Index and Abrasion Index results	108
Table 13.17	Grade of composite used in SGS-18-10 testwork	108
Table 13.18	Details of the variability composites used in tests SGS-40-10 and SGS-60-10	113
Table 13.19	Representative element concentrations	121
Table 13.20	Typical NaCN consumption, silver extraction, and cyanide concentrations	125
Table 14.1	Vein volumes and orientations	132
Table 14.2	Summary vein statistics	134
Table 14.3	Summary of thickness and accumulation by vein	136
Table 14.4	Grade and distance thresholds applied to extreme grade values	138
Table 14.5	Assignment of variogram models	140
Table 14.6	Variogram parameters applied to vein estimates	140
Table 14.7	Variogram parameters applied to host rock estimates	142
Table 14.8	Vein search parameters	146
Table 14.9	Host rock search parameters	147
Table 14.10	Specific gravity variogram parameters	151
Table 14.11	Specific gravity search parameters	151
Table 14.12	Comparison of estimated and input values	152
Table 14.13	La Preciosa Project mineral resource estimate effective 30 June 2011	156
Table 16.1	Open pit bench parameters	162

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 16.2	Mining dilution and minimum widths	163
Table 16.3	Dilutant grades	164
Table 16.4	Undiluted and diluted inventory above a 100 ppm Ag cut-off grade	164
Table 16.5	Pit optimisation parameters	165
Table 16.6	Mining costs used for pit optimisation	166
Table 16.7	Pit optimisation results	166
Table 16.8	Pit design parameters	168
Table 16.9	Summary of pit physicals	169
Table 16.10	Underground mining methods	171
Table 16.11	Underground feed mass and grade by panel dip	171
Table 16.12	Underground panel mass and grade	172
Table 16.13	Open pit mining capacity limits	175
Table 16.14	Underground mining capacity limits	175
Table 16.15	Mining schedule summary	177
Table 16.16	Potential mill feed breakdown by mineral resource classification	181
Table 16.17	Waste rock dump storage volumes	181
Table 16.18	Fleet requirements for major mining equipment	182
Table 17.1	Process consumables	185
Table 17.2	Process design criteria	185
Table 19.1	Marketing parameters	194
Table 21.1	La Preciosa Project preliminary initial capital cost estimates	201
Table 21.2	La Preciosa Project preliminary mining capital cost estimates	201
Table 21.3	La Preciosa preliminary processing and infrastructure capital cost estimates	202
Table 21.4	Other initial capital cost estimates	203
Table 21.5	Sustaining capital schedule	204
Table 21.6	Summary of La Preciosa Project preliminary operating cost estimates	204
Table 21.7	La Preciosa Project preliminary open pit operating cost estimates	205
Table 21.8	La Preciosa Project preliminary underground operating cost estimates	205
Table 21.9	La Preciosa Project preliminary processing and G&A cost estimates	206
Table 22.1	La Preciosa Project preliminary financial metric estimates	209
Table 22.2	La Preciosa Project preliminary economic summary (figures shown in \$M)	210
Table 22.3	Sensitivity analyses	211

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 25.1	La Preciosa Project mineral resource estimate effective 30 June 2011	215
Table 26.1	La Preciosa Project preliminary financial metric estimates(1)	218

Figures

Figure 4.1	La Preciosa Property land position location map	28
Figure 5.1	La Preciosa Property location and access map	33
Figure 5.2	Plan of proposed pits, dumps, tailings dam, plant, and infrastructure	35
Figure 5.3	Plan of land owner boundaries in the area of the proposed mine and plant facilities	36
Figure 7.1	Regional geological setting map	44
Figure 7.2	Example cross section of drillholes and lithology at 2701780 mN	45
Figure 7.3	Local geology plan	46
Figure 7.4	La Preciosa cross section at 2701780 mN showing drillhole traces, veins, and lithology	48
Figure 10.1	Location map of drillholes relative to mineral resource area	56
Figure 10.2	Cross section at 2701980 showing drillhole orientation relative to vein orientations	57
Figure 10.3	Plan of exploration targets	60
Figure 11.1	Graphs of all Orko standards for silver and gold	67
Figure 11.2	Graphs of the Orko-1 standard results for silver and gold	68
Figure 11.3	Graphs of the Orko-3 standard results for silver and gold by Inspectorate	69
Figure 11.4	Graphs of the Orko-3 standard results for silver and gold by SGS	69
Figure 11.5	Graphs of the Orko-6 standard results for silver and gold	70
Figure 11.6	Graphs of the Orko-8 standard results for silver and gold	71
Figure 11.7	Q-Q plots comparing silver and gold assays of pulp duplicates from Inspectorate and ALS Chemex	74
Figure 11.8	Scatterplots of blank assay silver and gold results	78
Figure 11.9	Graphs of the GBM908-13 and G308-7 standard results for silver and gold	80
Figure 11.10	Q-Q plot comparing silver and gold assays of pulp duplicates from SGS and Inspectorate	81
Figure 13.1	Silver and gold leaching kinetic curves	98
Figure 13.2	Cyanide consumption and silver extraction graphs	101
Figure 13.3	P80 grind size versus silver tailing grade	105
Figure 13.4	Grind % passing 200 mesh size versus silver tailing grades	106
Figure 13.5	Kinetic leaching time of silver extractions	106

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 13.6	Kinetic leaching time of silver extraction at P80 = 74 microns	107
Figure 13.7	Cyanide concentration and consumption with silver tailing grade	109
Figure 13.8	Kinetic silver leaching time at 40% solids	110
Figure 13.9	Cyanide concentration versus leached tailing silver grade at 40% solids	111
Figure 13.10	Grind versus silver tailing grade from tests SGS-18-09 and SGS-18-10	111
Figure 13.11	Cyanide concentration versus cyanide consumption	112
Figure 13.12	Silver extraction with and without lead nitrate	115
Figure 13.13	Silver extraction with and without lead nitrate by vein type	115
Figure 13.14	Comparison of silver feed grade vs silver tailing grade and silver extraction	117
Figure 13.15	Comparison of sulphur grade versus gold and silver extraction in botella tests on Martha composites	118
Figure 13.16	Metallurgical sample locations plotted on a horizontal projection of the deposit coloured by mineral resource grade and classification	120
Figure 13.17	Variability composite samples versus forecast silver grades	120
Figure 13.18	Silver feed versus tailing grades and extraction during botella tests	123
Figure 14.1	Oblique view from the SSW of vein projections	129
Figure 14.2	Oblique view of host rock estimation zones within 50 m of veins	150
Figure 14.3	Swath plot showing sample input and estimated silver grades for the Martha Alta vein	153
Figure 14.4	Grade tonnage curves by mining method and by classification	157
Figure 16.1	Example section showing undiluted and diluted vein	163
Figure 16.2	Pit shell tonnes and grade	167
Figure 16.3	Plan view of pit shells	168
Figure 16.4	Plan view of pit designs	169
Figure 16.5	Cross section through Pit 1 at 2702250 mN	170
Figure 16.6	Underground panels	173
Figure 16.7	Conceptual underground development with stoping panels	174
Figure 16.8	Mill feed by source	179
Figure 16.9	Open pit mining physicals	179
Figure 16.10	Underground development	180
Figure 16.11	Underground mining tonnages	180
Figure 16.12	Open pits and waste rock dumps	181
Figure 17.1	La Preciosa process flow sheet	188
Figure 18.1	La Preciosa processing facility plan	189

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 18.2	Tailings facility layout	190
Figure 18.3	Plan of the proposed access route from Durango to the Project site	191
Figure 18.4	Plan of the proposed power line route	192
Figure 18.5	La Preciosa Project proposed well field location	193
Figure 22.1	Cumulative cash flow graph	211
Figure 22.2	Sensitivity analysis spider graphs	212

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

1 Summary

This technical report has been prepared to disclose relevant information about the La Preciosa silver property (the Property). This information has resulted from additional mineral resource delineation drilling at the project (the Project), updated mineral resource estimates, and a preliminary economic assessment. This technical report supports the recently updated mineral resources at the La Preciosa silver property and the results of the preliminary economic assessment. The economic assessment is preliminary in nature. It includes Inferred mineral resources that are considered too speculative geologically to have the economic conditions applied to them that would enable them to be categorised as mineral reserves, and there is no certainty that the preliminary economic assessment will be realised.

1.1 Property description and ownership

This technical report refers to the Property, an advanced stage silver exploration project located approximately 84 kilometres (km) by road northeast of the city of Durango, in Durango State, México. In October 2009, Pan American Silver Corp. (Pan American), Orko Silver Corp. (Orko), PASMEX S.A. de C.V. (PASMEX, a subsidiary of Pan American which holds Pan American's interest in the Project) and Proyectos Mineros La Preciosa S.A. de C.V. (the La Preciosa JV Company) entered into a formal joint venture agreement in connection with the Project. Under the terms of the joint venture agreement, PASMEX acts as the Project operator and Pan American can earn a 55% interest in the joint venture by bringing the Project into production.

As of the end of 2010, Pan American had invested approximately \$14 million on over 90,000 metres of exploration and infill mineral resource drilling, metallurgical testing, engineering activities to evaluate alternative extraction and development scenarios to maximize the Project's economics, baseline environmental studies, and community relations work.

1.2 Geology and mineralisation

The Property comprises a block of mineral exploitation concessions covering an area of approximately 1,134 hectares (ha) located on the eastern flank of the Sierra Madre Occidental mountain range. Cretaceous age conglomerate and Tertiary age andesitic volcanic rocks are the main hosts of Tertiary age epithermal quartz veins containing economic levels of silver and gold mineralisation, as well as barite and lesser quantities of base metals, primarily zinc and lead. Two major vein and vein breccia systems are exposed on hills and ridges on either side of an approximately 800 metre (m) wide valley. The dominant geological feature on the Property is the northwest-trending La Preciosa Ridge which hosts the dominantly north-striking and westward-dipping main vein system, which includes the Martha, Abundancia, Gloria, Pica, Luz Elena, Sur, and Nueva veins. These veins are cross-cut by east-striking, south-dipping Transversal veins. The major vein breccia system to the east of La Preciosa Ridge on the eastern side of the valley floor includes the northwest striking Zona Oriente and Zona Oriente Extension, which is believed to be the surface expression of the Martha vein.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

1.3 Status of exploration, development, and operations

On the order of 30,000 tonnes (t) of material from the La Gloria and Abundancia veins was removed by historical mining dating from the late 1800s. Underground workings are accessible on the La Gloria and Abundancia veins over a distance of approximately 2.5 km at the north end of the La Preciosa Ridge. Approximately 10,000 t of stockpiled mineralised material is present on the surface above the old workings. Historical underground workings are also found at the south end of the ridge. Aside from drill access roads and buildings to support drill core processing activities and core storage, no other development has been made on the Property and there are no active mining operations.

Numerous mineralised vein structures have been identified by nearly 1,000 drillholes and underground channel samples principally

distributed over an area of approximately 850 ha. A total of 18 different veins tested by 677 drillholes have demonstrated sufficient geological continuity for estimation of mineral resources.

1.4 Mineral resource estimate

The most recently estimated mineral resources effective 30 June 2011 (shown in Table 1.1) and the results of a preliminary economic assessment based on these mineral resources are disclosed in this technical report. No mineral reserves have been estimated for the Project. Additional infill drilling is recommended to upgrade Inferred mineral resources to Indicated for conversion to mineral reserves as the Project progresses. A number of continuous improvement recommendations have been made in the relevant sections of this report to increase confidence in the data used to estimate mineral resources.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 1.1 La Preciosa Project mineral resource estimate effective 30 June 2011

Mining method	Classification	Cut-off grade Ag ppm	Tonnes (millions)	Ag ppm	Silver million ounces	Au ppm	Gold thousand ounces	Silver equivalent ppm	Silver equivalent million ounces
Open pit	Indicated	35	10.9	129	45	0.19	66	139	49
Open pit	Inferred	35	7.6	74	18	0.13	31	81	20
Underground	Indicated	85	13.9	152	68	0.35	156	170	76
Underground	Inferred	85	7.6	117	28	0.21	52	128	31
Total	Indicated		24.8	142	113	0.28	222	156	124
	Inferred		15.2	96	46	0.17	83	105	51

Notes:

Mineral resources that are not mineral reserves do not have demonstrated economic viability. CIM (2010) defines a mineral reserve as the economically mineable part of a Measured or Indicated mineral resource demonstrated by at least a preliminary feasibility study. No mineral reserves have been estimated. Mineral resources have accounted for minimum mining width and planned mining dilution.

The estimate of mineral resources may be materially affected by environmental, permitting, legal, title, taxation, socio-political, marketing, or other relevant issues, but no such issues have been identified at this time.

Tonnes, grades, and ounces have been rounded and this may have resulted in minor discrepancies in the totals. Grades are expressed in parts per million (ppm) which is equivalent to grams per tonne (g/t).

Cut-off grades are based on operating cost estimates and metal prices of \$25 per ounce silver (Ag) and \$1,250 per ounce gold (Au). Metal prices are based on a weighted average of historical three year average daily silver prices and a two year future price forecast.

The division between open pit and underground mineral resources is set on a horizontal level at the 1920 m elevation, which is considered close to optimum at the metal prices and operating costs assumed in this preliminary economic assessment.

Silver equivalent grade values assume a gold to silver ratio of 50 to 1 based on the assumed metal prices. The metallurgical recoveries and refining charges are assumed to be the same for silver and gold for the purposes of the equivalence calculation only.

1.5 Mining methods and Project infrastructure

Mineralisation at the Project will be exploited using both open pit and underground mining methods. Open pit mining will be undertaken using conventional truck and shovel techniques. The veins at the Property vary widely in both width and dip to an extent that the choice of a single underground mining technique will not be appropriate for all veins. Shrinkage stoping was identified as the most appropriate method for steeply dipping veins (greater than 70°) and room and pillar (with backfill where the width requires it) was considered appropriate for shallow dipping veins (less than 35°).

The Property is not yet connected to the commercial electrical grid but a nearby village and a town are serviced by the commercial electrical grid. The Property is presently supplied electrical power by one 65 kilowatt (kW) diesel generator and two smaller 5.5 kW diesel generators. The main power grid for Durango follows a paved federal highway and a power connection is available for the Project from a substation located in the city of Canatlán, Durango, 41 km northwest of the Project site.

A nearby town has a gas station and the services of metal fabricators and mechanic shops. A railway line is present near the south boundary of the Property and the railway has a direct line to Torreon, the site of the nearest metal smelter.

The water for drilling and services is obtained from a water reservoir in a nearby village. Water for mining production is proposed to be supplied from an underground source

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

in the thick gravels on the plain to the east of the Project, accessed by drilling a 200 m deep water well 7.2 km to the east of the Project.

Presently the Property has six core storage sheds, an office, lunch room, washrooms, small warehouse, flammable substances storage area, drilling company workshop, night watchman s accommodation, and a generator/core cutting shed.

The proposed main processing facilities for the Project will include primary crushing, grinding, leaching, counter current decantation, tailings detoxification, silver and gold precipitation, refining, and tailings disposal facilities. In addition to the main process facilities, there will be several surface buildings constructed to support the mining and process operations. These facilities include administration, security, warehouse, change house, explosives storage, and truck shop buildings, and truck wash and mill maintenance facilities.

1.6 Capital and operating costs and economic analyses

Based on the mineral resource estimate and some economic assumptions, Snowden has developed a detailed mine plan and schedule, and incorporated assumptions with respect to metallurgical recovery, mining recovery, and dilution. This plan has resulted in an estimation of capital costs as detailed in Table 1.2 and operating costs as summarised in Table 1.3. The average life-of-mine cash costs were estimated at \$11.84 per ounce of silver, net of gold by-product credits.

Table 1.2 La Preciosa Project preliminary capital cost estimates

Type	\$ Million
Open pit mining equipment	25.9
Underground mining equipment	15.8
Open pit pre-strip	4.4
Underground capital development	3.7
Plant	143.3
EPCM	22.1
Owner s costs	47.9
Escalation of plant and EPCM costs	6.4
Total estimated capital(1)	269.5

Note(1): Excludes sustaining capital. EPCM is engineering, procurement, and construction management costs

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 1.3 La Preciosa Project preliminary operating cost estimates

Cost type	\$/Tonne	\$/Tonne milled
Open pit reference mining (\$ per tonne of waste)(1)	1.11	
Open pit reference mining ((\$ per tonne of feed)	1.45	
Underground mining (\$ per tonne of feed)	31.49	
Total mining		26.60
Processing (\$ per tonne of feed)		16.64
General and administration (\$ per tonne of feed)		2.57
Average total cost(2) (\$ per tonne of feed)		45.81

Note(1): Reference costs are at pit crest. Mining cost increases with depth.

Note(2): Excludes taxes and royalties.

The metal prices used in this technical report are based on a weighted average calculation of the historical prices (weight 60%) and future forecast prices (weight 40%) as of the end of June, 2011.

For the calculation of the silver price used in this technical report, the historical price of US\$19.44 is the average of the London Bullion Market daily silver prices for the 36 months prior to the end of June, 2011. The future price of \$33.70 is the 24 month future price forecast on the Chicago Mercantile Exchange (previously the Comex futures division of NYMEX). The weighted average price of \$25.14 was rounded down to \$25.00.

For the calculation of the gold price used in this technical report, the historical price of US\$1,110.70 is the average of the London Bullion Market daily PM gold prices for the 36 months prior to the end of June, 2011. The future price of \$1,491.38 is the 24 month future price forecast on the Chicago Mercantile Exchange. The weighted average price of \$1,262.98 was rounded down to \$1,250.

Based on the costs, the plan and schedule, and the commodity prices, the financial outcomes that were derived for the Property are shown in Table 1.4. These outcomes include allowances for taxes and royalties as detailed in Section 22.1.

Table 1.4 La Preciosa Project preliminary financial metric estimates(1)

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Measure	Units	Value(2)
Undiscounted present value	\$ Million	497.0
Net present value at 5% discount p.a.	\$ Million	314.6
Net present value at 10% discount p.a.	\$ Million	191.2
Internal rate of return	%	24.3
Payback period	Years	3.3

Note(1): The economic assessment is preliminary in nature. It includes Inferred mineral resources that are considered too speculative geologically to have the economic conditions applied to them that would enable them to be categorised as mineral reserves, and there is no certainty that the preliminary economic assessment will be realised.

Note(2): Based on metal prices of \$25/oz silver and \$1,250/oz gold. Inclusive of taxes, royalties, and a management fee of 5% of operating costs (\$50.9 million) and 5% of initial capital costs (\$13.5 million) paid to the operator.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

1.7 Mineral processing, metallurgical testing, and recovery methods

In the period from 2007 to 2010 a total of 865 samples from diamond drill core were used to prepare 44 metallurgical composites, including 28 variability composites. They were studied at two independent commercial laboratories to evaluate the response to gravity and flotation concentration and agitation cyanidation.

Whole ore agitation cyanidation was determined to be the most favourable processing option. At the currently estimated global plant feed grade of 137 parts per million (ppm) silver (Ag), the data forecasts a laboratory silver extraction of 86%. Gold extraction is affected by oxidation with a nominal 70% extraction in the sulphide zones increasing to 90% in some of the oxidised zones, with an overall forecast of 78% gold extraction.

The consumption of cyanide has been quite variable. Although the majority of the test work reported consumption of less than 1.3 kilograms per tonne (kg/t), some tests were as high as 6 kg/t (which is considered to be a high rate of cyanide consumption), where favourable metallurgical results were reported. Additional testing will be required to better understand the reported high cyanide consumptions. It is anticipated that to the extent that elevated cyanide consumption is encountered in operation, the cyanide concentration in the plant solutions will be permitted to decrease below the optimum of 2 grams per litre (g/l), incurring a few percent loss in silver extraction but a net gain as a result of lower cyanide costs.

The deposit benefits from fine grinding to at least P80 = 74 microns (80% passing 200 mesh) with a leaching time that is expected to be in the range of three to four days. Small quantities of copper and zinc are leached in the process and report to the pregnant solution as cyanides. They will be destroyed in the operating plant cyanide destruction circuit.

A two staged laboratory test programme is recommended in which the first stage will determine the role of pH. The second stage should comprise another variability testing programme to confirm the silver and gold tailings grades by ore type, establish crushing and grinding work indices including JK drop weight, and cyanide destruction. The results of this programme may alter the feasibility study stage design criteria and therefore impact the capital and operating costs, particularly so in the grinding circuit.

The plant facilities for the Project have been designed for a throughput of 5,000 dry metric tonnes per day. Feed grade material will be processed by crushing and grinding prior to cyanide leaching. Recovery of soluble metals will be accomplished by multi-stage counter current decantation followed by zinc precipitation. The precipitate will be further refined through smelting and will yield a doré product for sale that will contain the silver and gold produced at the Project. Leach tailings will go through cyanide detoxification with sulphur dioxide prior to discharge at the tailings facility. The tailings facility will be of conventional construction utilising multiple spigot discharge points and a reclaim barge. A tailing facility containment dam will be constructed from mined waste or surface quarry material.

1.8 Environmental studies, permitting, and social and community impact

Reporting of the environmental baseline data collected for a full year between 2010 and 2011 has been completed for the Project. The baseline data will be used to compile the environmental impact statement (MIA), which will be submitted to the Mexican

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

government for approval prior to the issuing of construction and operation permits. The most likely significant environmental issues that may be related to the permitting of the Project include long-term water quality and quantity management, securing water rights, protracted approval and permitting processes, long-term management of metal leaching and acid rock drainage (MLARD), construction and operation of the access road, social issues, securing surface rights, and management and liner considerations for the tailings impoundment facility. The main documents to be prepared and submitted to obtain construction and operation permits are the MIA, a forest land use modification, a risk analysis, and an archaeological study report.

Likely social concerns surrounding the development of the Project include acquisition of surface land, water use, perceptions of the cyanide facility and the use of cyanide, operation of the access road, potential imposition of access restrictions to the area, and the expectations that the Project development may generate in surrounding communities with respect to employment and quality of life.

It is recommended that a programme be commenced to acquire rights to the land in the area of the Project which will allow the infrastructure to be commissioned on the Property. The access rights will include the area for the well, transmission corridors, mine and mill areas, tailings storage facility, buffer zone, etc. As water supply is critical to the success of the Project, it is recommended that water rights required for the facility also be acquired. An extensive community engagement process should also be immediately established.

Consideration should be given to continue to collect environmental data beyond the baseline data required for the MIA. The activities to be considered include:

- The installation of a weather station for meteorological data collection.

- The installation of monitoring wells and piezometers for open pit areas as well as upstream and downstream from the tailings storage facilities and process plant to monitor ground water characteristics.

- Design and implementation of an environmental monitoring programme.

- Dust monitoring.

- Complete static and kinetic testing for MLARD which will be coupled with an ongoing monitoring programme for waste rock and tailings.

1.9 Conclusions and recommendations

With a net present value of \$315 million at a 5% discount rate, an internal rate of return of 24.3%, and a Project payback of 3.3 years, the Project is sufficiently robust that, at the metal prices used in this analysis (\$25 per ounce silver and \$1,250 per ounce gold), there is a reasonable likelihood that the Project will proceed following the completion of a feasibility study.

On the basis of the results of this preliminary economic assessment, the recommendation is made to proceed to a feasibility study. The expected cost of completing the feasibility study, from the issuing of the preliminary economic assessment forward, has been estimated at \$8 million (excluding the acquisition costs of land and water rights).

Inferred mineral resources will be excluded from the estimates forming the basis of the recommended feasibility study, as required by CIM (2010), which will impact the feasibility study financial outcomes.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

1.10 Cautionary note regarding forward-looking information and statements

This preliminary economic assessment is preliminary in nature. It includes Inferred mineral resources that are considered too speculative geologically to have the economic conditions applied to them that would enable them to be categorised as mineral reserves, and there is no certainty that the preliminary economic assessment will be realised.

Certain of the statements and information in this Technical Report constitute forward-looking statements within the meaning of the United States Private Securities Litigation Reform Act of 1995 and forward-looking information within the meaning of applicable Canadian Provincial securities laws. All statements, other than statements of historical fact, are forward-looking statements. When used in this Technical Report the words estimates, expects, projects, plans, contemplates, calculates, objective, potential, and other similar words and expressions, identify forward-looking statements or information. These forward-looking statements or information relate to, among other things: the future successful development of the Project; the estimates of expected or anticipated economic returns, as reflected in the preliminary economic assessment; the timing for completion of a feasibility study and environmental impact assessment on the Project; future production of silver and gold and mine-life of the Project; future cash costs per ounce of silver; the price of silver and gold; the sufficiency of Pan American's current working capital, anticipated operating cash flow or its ability to raise necessary funds; the capital necessary to construct a mine at the Project and the time-line for such construction; the accuracy of mineral resource estimates; estimated production rates for silver and other payable metals produced at the Project; timing of production and the cash and total costs of production; the estimate of metallurgical recoveries for silver and gold; the estimate for mining dilution; the estimated cost of and availability of funding necessary for sustaining capital; and ongoing or future development plans and capital replacement, improvement or remediation programmes.

These statements reflect current views with respect to future events and are necessarily based upon a number of assumptions and estimates that, while considered reasonable, are inherently subject to significant business, economic, competitive, political and social uncertainties and contingencies. Many factors, both known and unknown, could cause actual results, performance or achievements to be materially different from the results, performance or achievements that are or may be expressed or implied by such forward-looking statements contained in this Technical Report and assumptions and estimates have been made based on or related to many of these factors. Such factors include, without limitation: fluctuations in spot and forward markets for silver, gold, base metals and certain other commodities (such as natural gas, fuel oil and electricity); fluctuations in currency markets (such as the Mexican Peso versus the United States Dollar); changes in national and local government, legislation, taxation, controls or regulations and political or economic developments, particularly in Mexico and in Canada; risks and hazards associated with the business of mineral exploration, development and mining (including environmental hazards, industrial accidents, unusual or unexpected geological or structural formations, pressures, cave-ins and flooding); employee relations; relationships with and claims by local communities and indigenous populations; availability and increasing costs associated with mining inputs and labour; the speculative nature of mineral exploration and development, including the risks of obtaining necessary licenses and permits and the presence of laws and regulations that

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

may impose restrictions on mining; diminishing quantities of grades of mineral reserves as properties are mined; global financial conditions; challenges to, or difficulty in maintaining, title to properties and continued ownership thereof; the actual results of current exploration activities, conclusions of economic evaluations, and changes in Project parameters to deal with unanticipated economic or other factors; increased competition in the mining industry for properties, equipment, qualified personnel, and their costs; and, with respect to Pan American, those factors identified under the caption "Risks related to Pan American's business" in Pan American's most recent Form 40F and annual information form filed with the United States Securities and Exchange Commission and Canadian provincial securities regulatory authorities. Investors are cautioned against attributing undue certainty or reliance on forward-looking statements. Although Pan American and Orko have attempted to identify important factors that could cause actual results to differ materially, there may be other factors that cause results not to be as anticipated, estimated, described, or intended. The companies do not intend, and do not assume any obligation, to update these forward-looking statements or information to reflect changes in assumptions or changes in circumstances or any other events affecting such statements or information, other than as required by applicable law.

September 2011

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

2	Introduction
---	--------------

This technical report has been prepared by Snowden Mining Industry Consultants Inc. (Snowden) for Pan American Silver Corp. (Pan American) and Orko Silver Corp. (Orko), in compliance with the disclosure requirements of Canadian National Instrument 43-101 (NI 43-101), to support disclosure of the results of a preliminary economic assessment of the Property. This disclosure includes information from additional mineral resource delineation drilling, updated mineral resource estimates, and a preliminary economic assessment.

The effective date of this technical report is 30 June 2011. The Project drilling data cut-off date for mineral resource estimation was 25 October 2010. The economic analysis to determine the appropriate cut-off grades for reporting mineral resources and for the subsequent mining study was completed on 30 June 2011. No new material information has become available between these dates and the signature date given on the certificate of the qualified persons.

This preliminary economic assessment is preliminary in nature. It includes Inferred mineral resources that are considered too speculative geologically to have the economic conditions applied to them that would enable them to be categorised as mineral reserves, and there is no certainty that the preliminary economic assessment will be realised. Mineral resources that are not mineral reserves do not have demonstrated economic viability. No mineral reserves have been estimated.

Pan American is a silver mining and exploration company listed on the Toronto Stock Exchange (TSX:PAA) and the NASDAQ (NASDAQ:PAAS) stock exchange. Orko is a silver exploration company listed on the TSX Venture Exchange (TSX.V: OK.).

Unless otherwise stated, information and data contained in this report or used in its preparation have been provided by Orko and Pan American. This technical report has been compiled from sources listed in the References Section and cited in the text by Mr. Anthony Finch, P.Eng., M.AusIMM, Divisional Manager, Mining Engineering of Snowden, Mr. Michael Stewart, M.AIG, Principal Consultant of Quantitative Geoscience Pty. Ltd. (QG), Mr. Joshua Snider, P.E., Engineer with M3 Engineering & Technology Corporation. (M3), Mr. Thomas Drielick, P.E., Senior Vice President with M3, and Mr. Gary Hawthorn, P.Eng., Owner of Westcoast Mineral Testing, Inc.. Mr. Finch, Mr. Stewart, Mr. Snider, Mr. Drielick, and Mr. Hawthorn are qualified persons as defined by NI 43-101 and are independent of Pan American and Orko. The responsibilities of each co-author are provided in Table 2.1.

Mr. Snider visited the Project site on 9 June 2010, accompanied by Hernán Dorado Smith, Senior Planning Engineer of Pan American. Mr. Snider reviewed the site with emphasis on process plant and tailings locations.

Mr. Finch and Mr. Stewart visited the Project site on 5 July 2011, accompanied by Ms. Pamela De Mark, Director of Resources, Samuel Coronado, La Preciosa Project Manager, Sergio Morfín, Exploration Manager México, and Hernán Dorado Smith, Senior Planning Engineer, all representatives of Pan American. Mr. Finch reviewed the potential pit locations, the portal and the dump locations, as well as the general

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

infrastructure and access to the Project site. Mr. Stewart reviewed representative drill core intersections of the veins and surrounding host rock located at the core storage facility on the Project site, confirmed the collar coordinates of selected drillholes, visited

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

outcrops of the Martha, Gloria, Abundancia, and Transversal veins, reviewed paper and digital geological interpretations, and reviewed the geological database.

Because a current personal inspection has been conducted by other qualified persons responsible for the preparation of this technical report, and no additional beneficial information would have been derived from a site visit at this stage of the Project, Mr. Hawthorn and Mr. Drielick did not conduct a site visit.

Table 2.1 Responsibilities of each qualified person

Qualified person	Company	Responsible for sections
Anthony Finch	Snowden Mining Industry Consultants Inc.	1: Summary; 2: Introduction; 3: Reliance on Other Experts; 4: Property Description and Location; 5: Accessibility, Climate, Local Resources, Infrastructure and Physiography; 12: Data Verification; 15: Mineral Reserve Estimates; 16: Mining Methods; 19: Market Studies and Contracts; 20: Environmental Studies, Permitting and Social or Community Impact; 21: Capital and Operating Costs; 22: Economic Analysis; 24: Other relevant data and information; 25: Interpretation and Conclusions; 26: Recommendations; 27: References
Michael Stewart	Quantitative Geoscience Pty. Ltd.	1: Summary; 2: Introduction; 6: History; 7: Geological Setting and Mineralisation; 8: Deposit Types, 9: Exploration; 10: Drilling; 11: Sample Preparation, Analyses and Security; 12: Data Verification; 14: Mineral Resource Estimates; 23: Adjacent Properties; 25: Interpretation and Conclusions; 26: Recommendations
Joshua Snider	M3 Engineering & Technology Corp.	1: Summary; 2: Introduction; 12: Data Verification; 18: Project Infrastructure; 21: Capital and Operating Costs; 25: Interpretation and Conclusions; 26: Recommendations
Thomas Drielick	M3 Engineering & Technology Corp.	1: Summary; 2: Introduction ; 12: Data Verification; 17: Recovery Methods; 25: Interpretation and Conclusions; 26: Recommendations
Gary Hawthorn	West Coast Mineral Testing Inc.	1: Summary; 2: Introduction ; 12: Data Verification; 13: Mineral Processing and Metallurgical Testing; 25: Interpretation and Conclusions; 26: Recommendations

Unless otherwise stated, all units are metric and currencies are expressed in US dollars (\$). Project data coordinates are based on the International Terrestrial Reference System (ITRS), which is similar to within a few centimetres of the World

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Geodetic System (WGS) 84, the coordinate system used by the Global Positioning System (GPS).

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

3 Reliance on other experts

The qualified persons preparing this technical report have relied on the reports, opinions, and statements of experts who are not qualified persons as defined by NI43-101. Information regarding environmental aspects of the Property has been provided by Wade Stogran, Director, Environmental Affairs of Pan American, who is not a qualified person. Information regarding land occupancy and lease agreements has been provided by one of the La Preciosa JV Company's legal counsel in Durango, Mexico, Mr. Eduardo Bravo Campos, now deceased.

In development of the mineral inventory for this assessment Snowden has based its geotechnical design criteria on a report written by Golder Associates (Golder, 2010). This report was commissioned by Pan American to assess the geotechnical aspects of mining at the Project in both the underground and the open pit environments.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

4 Property description and location

Information in this section is updated from Mine Development Associates (MDA, 2009).

4.1 Location, mineral tenure, and surface rights

The Property is located approximately 84 kilometres (km) by road northeast of the City of Durango in Durango State, México. The centre of the mineral resources are at 2,702,000 North, 555,400 East in the Universal Transverse Mercator (UTM), North American Datum of 1927 (NAD 27).

The Project is located within eight concessions with a total area of 1,134.1 hectares (ha). Each corner of each concession is surveyed by a licensed surveyor with reference to the location of a claim monument. The Property is surrounded by the Santa Monica and San Juan properties, which are also controlled by the La Preciosa JV Company. A map of the Property land position is shown in Figure 4.1 at three different scales.

Details of the concessions, including the expiration date of the claims, are given in Table 4.1. The La Preciosa JV Company holds 100% of the registered and beneficial title in the Properties, free and clear of all encumbrances (other than liens in favour of government authorities as reflected by the terms of the mineral leases, licenses and permits and all obligations arising from any royalty or similar agreements existing on the effective date of the joint venture agreement in favour of government authorities), except as discussed in Section 4.3.

The La Preciosa JV Company has entered into a series of contracts with local landholders and Ejido Councils (farm owners collective) in order to conduct exploration on their land. Separate contracts are held to maintain free access to the site. New negotiations will be required to either purchase land or to obtain long term agreements for the future Project operations.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 4.1 La Preciosa Property land position location map

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Note: black lines are lease boundaries controlled by the La Preciosa JV Company, black shaded areas are third party land holdings, and red shaded area is the vein interpretation.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 4.1 La Preciosa Property concession details

Claim name	Expedient	Title	Issue date	Area (ha)	\$MXP(1) per ha	Total \$MXP(2)	Expiry date
La Preciosa property concessions							
La Preciosa	321.1-2/398	182517	15/07/1988	143.6119	111.270	15,980	14/07/2038
Lupita	321.1/9-303	182584	12/08/1988	27.1878	111.270	3,025	11/08/2038
Fracción La Preciosa	321.1/2-399	185128	14/12/1989	2.5249	111.270	281	13/12/2039
San Patricio	321.42/919	189616	05/12/1990	29.474	111.270	3,280	04/12/2040
La B	2/1.3/01962	214232	06/09/2001	28.2006	111.270	3,138	05/09/2051
El Choque Tres	2/1/02251	218953	28/01/2003	10.0	63.220	632	27/01/2053
El Choque Cuatro	25/30812	220251	02/07/2003	644.1296	31.620	20,367	01/07/2053
El Choque Seis	25/31144	220583	02/09/2003	249.0	31.620	7,873	01/09/2053
Adjacent concessions controlled by the La Preciosa JV Company							
Santa Monica	25/31208	221288	20/01/2004	16385.457	31.620	518,108	19/01/2054
Santa Monica Sur	25/31411	223097	15/10/2004	900.0	31.620	28,458	14/10/2054
San Juan	25/31434	226663	17/02/2006	14003.4737	15.72	220,135	16/02/2056

Note(1): MXP = Mexican Pesos. Note(2): Fees are payable twice per year and are due every January and July.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

4.2 Issuer's interest

On 13 April 2009, Pan American and Orko announced that they had signed a letter agreement setting out the basic terms under which they may jointly develop the Project. Pursuant to the letter agreement, Pan American agreed to act as operator and, in order to retain a 55% interest in the Project, to (i) make a minimum of \$5,000,000 in expenditures relating to exploration of the properties within 12 months of executing the letter agreement, (ii) prepare a feasibility study in respect of the Project within 36 months of executing the letter agreement, and (iii) following a positive construction decision by the parties, contribute 100% of the funds necessary to develop and construct an operating mine as contemplated in the feasibility study.

In October 2009, Pan American, Orko, (PASMEX, a subsidiary of Pan American which holds Pan American's interest in the La Preciosa Project and which is the operator) and the La Preciosa JV Company entered into a formal joint venture agreement in connection with the Project.

Pursuant to the terms of the joint venture agreement dated 13 April 2009, if PASMEX fails to complete the required expenditures during the first 12 months or to complete the feasibility study within the 36-month period, PASMEX will surrender its interest in the La Preciosa Project. If, however, PASMEX incurs the required expenditures during the first 12 months and completes the feasibility study within the allotted period, but elects not to proceed with funding the construction of the Project, PASMEX will surrender its 55% interest but will be entitled to receive a 1.5% net smelter return royalty on the Project as provided in the joint venture agreement. Orko or the La Preciosa JV Company have the right to purchase the net smelter return royalty from PASMEX for \$8,000,000 for a period of three years from the date of the surrender of the Pan American interest.

4.3 Royalties, back-in rights, payments, agreements, and encumbrances

The Project is subject to the San Juan Property Option Agreement dated April 10, 2006, among Orko and the Silver Standard Group, in accordance of which the La Preciosa JV Company pays the La Cuesta Royalty, comprised of \$5,000 or 2% of direct exploration costs, and 0.25% of net smelter returns.

Additionally, there is a Net Smelter Return Royalty Agreement dated 19 June 2002 among Minas Luismin S.A. de C.V., Minas Sanluis, S.A. de C.V. and Corporación Turística Sanluis, S.A. de C.V. (CTS) which runs with the Property and grants a 3% net smelter returns royalty to CTS on minerals derived from the La Preciosa, Lupita, Fracción La Preciosa, San Patricio, El Choque Tres, and La B claims.

For this preliminary economic assessment, El Choque Cuatro and El Choque Seis are also included in economic model but they are not subject to any royalties. Therefore, based on the estimated feed grade tonnes to be extracted from the various claims, a weighted average net smelter royalty of 2.5% is applied in the economic model.

There are no other known royalties, back-in rights, payments, agreements, or encumbrances.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

4.4 Environmental liabilities

A stockpile of approximately 10,000 tonnes (t) of material produced from the historical workings is located towards the north end of La Preciosa Ridge and there are small historical workings over some of the veins. These do not present a significant environmental liability and will be processed as plant feed.

Nearby farmers produce beans and maize and local cattle graze on neighbouring land. There are a number of unpaved access roads on the Property as well as minor infrastructure to support exploration and drilling activities. The major environmental issue in the area is the current cattle, goat and agricultural regime that tends to exceed the carrying capacity of the area.

4.5 Permits

Pan American has obtained five exploration permits from the Secretaría de Medio Ambiente y Recursos Naturales (Ministry of Environment and Natural Resources, SEMARNAT) since the start of Pan American's involvement in the Project. Data collection work is complete to compile the database of vegetation, wildlife, ground and surface water quality and quantity, climate, and other items necessary for submission of the MIA (Environmental Impact Assessment). The database summary report has been completed and the information from that report will be used for compiling the MIA for submission to and approval by SEMARNAT. Pan American has obtained contracts and agreements with the owners of the Property for exploration and will need the same for mining.

4.6 Significant factors and risks

The Property is subject to the same risks as any other mining project in México or in other newly industrialised nations, including under-estimation of capital and/or operating costs, delays or inability in securing land agreements, the inability to attract qualified personnel, personal security risks, poor communication with stakeholders, over-estimation of mineral resources and metal prices, inflation of capital and/or operating costs, complicated geotechnical conditions, and changes in the Project mine plan. There are no other known significant factors and risks that may affect access, title, or the right or ability to perform work on the Property.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

5 Accessibility, climate, local resources, infrastructure and physiography

Information in this section is updated from MDA (2009).

5.1 Access

The Property is located approximately 84 km by road northeast of the city of Durango and can be accessed by vehicle from Durango in approximately 90 minutes. A Google satellite map showing the location of the Property relative to Durango and the access roads is shown in Figure 5.1. From Durango, travel is northeast toward Torreon by the sealed Federal Highway 40 to the town of Francisco I. Madero. From this point a secondary paved road is followed northwest to the village of Lázaro Cardenas, then by a newly paved road to the village of Francisco R. Serrano. After 9 km there is a turnoff on a newly paved road southwest to the village of Francisco Javier Mina, then travel is to the south for 5.5 km by gravel road to the access road to the Project site. The access road is a 3.5 km gravel road heading southeast and leads to the portal of the historic workings and the main camp of the Project.

Figure 5.1

La Preciosa Property location and access map

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

5.2 Climate and length of operating season

The Property area has a semi-arid climate, with an annual average temperature of about 25°C and an average annual precipitation of about 600 millimetres (mm), usually occurring between May and October. Temperatures can fall below freezing on winter nights but snow is rare. Activities can take place year round. The dominant wind direction is southeast.

5.3 Proximity to population centre and transport

Durango is the capital city of Durango State and has a population of approximately 600,000. One of the major industries in Durango is mining, particularly for silver, and the region is a good source of skilled personnel, support services, and mining equipment. The city of Durango is served by an international airport with daily flights connecting to destinations in México and the United States. Durango is located on Mexican Federal Highway 40 which connects Durango to Mazatlan approximately 310 km to the southwest on the Pacific coast and to Torreón approximately 245 km to the northeast. A rail line runs between Durango and Torreón and connects to other cities in México and the United States.

5.4 Surface rights, land availability, infrastructure, and local resources

5.4.1 Surface rights, land availability, and mining areas

The Property has ample land for the construction of the mine, mill, and supporting facilities including tailings and waste disposal. A plan of the proposed pits, dumps, tailings dam, plant, and infrastructure is shown in Figure 5.2

Surface rights are coordinated through agreements with the Ejido Councils (farm owners collective). Any future surface utilisation or construction will require negotiating with the Ejido Councils involved. Separate surface access contracts are also in place with some independent ranch owners who are not members of Ejido Councils. Details of the landowners in the area of the proposed mine and plant facilities are shown in Table 5.1. A plan of the land owner boundaries is shown in Figure 5.3.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 5.2 Plan of proposed pits, dumps, tailings dam, plant, and infrastructure

Table 5.1 Land owners in the area of proposed mine and plant facilities

Name and property type

Area (ha)

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Candelaria Uves Solórzano	private	200
Petra Higuera	private	55
Ciro Diaz	private	100
Ricardo Flores Magón	Ejido	150
Lázaro Cárdenas	Ejido	101
La Preciosa	La Preciosa Resources	45

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 5.3 **Plan of land owner boundaries in the area of the proposed mine and plant facilities**

5.4.2 Power, infrastructure, and water

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Both the quality of infrastructure and the population density increases towards the city of Durango. The Property is not connected to the commercial electrical grid but the nearby village of Francisco Javier Mina (population around 920) and the town of Francisco I. Madero (population around 4,550) are serviced by the commercial electrical grid. The Property is presently supplied electrical power by one 65 kilowatt (kW) diesel generator and two smaller 5.5 kW diesel generators. The main power grid for Durango follows a paved federal highway and a power connection is available for the Project from a substation located in the city of Canatlán, Durango, 41 km northwest of the Project site.

The town of Francisco I. Madero has a Pemex gas station and the services of metal fabricators and mechanic shops. A railway line is present near the south boundary of the Property and the railway has a direct line to Torreon, the site of the nearest metal smelter.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Presently the Property has six core storage sheds, an office, lunch room, washrooms, small warehouse, flammable substances storage area, drilling company workshop, night watchman s accommodation, and a generator/core cutting shed.

The water for drilling and services is obtained from a water reservoir in Francisco Javier Mina, charged at a rate of \$500 Mexican Pesos per 1.75 cubic metres (m³), including the cost to haul the water to the Project by tanker trucks to water tanks located adjacent to the drilling areas. Water for mining production is proposed to be supplied from an underground source in the thick gravels on the plain to the east of the Project. The underground source will be accessed by drilling a well 200 metre (m) deep on the Ejido Lázaro Cardenas property located 7.2 km to the east of the Project. The cost for the installation of the well is anticipated to be on the order of \$700,000.

The fee for industrial use of the water as imposed by the Mexican National Water Commission (CONAGUA) is \$7.1623 Mexican Pesos per m³ of water. The area in which the water well is proposed does not require a permit to initialise construction, however, once the well is complete and operational it must be registered with CONAGUA, which administers water management at the federal level.

5.4.3 Local resources and mining personnel

There is a sufficient local work force available in Durango and the surrounding region for Project construction and operators, details are shown in Table 5.2.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 5.2 La Preciosa Project work force availability

Federal code	State	Municipality code	Municipality	Local code	Locality	Total population	Active population	Distance to Project (km)
10	Durango	1	Canatlán	1	Canatlán	11,495	4,285	43
10	Durango	1	Canatlán	110	Ricardo Flores Magón	1,467	479	13
10	Durango	5	Durango	1	Victoria de Durango	518,709	204,350	84
10	Durango	5	Durango	295	Vicente Suárez	92	31	48
10	Durango		Pánuco de Coronado					
		20	Coronado	1	Francisco I. Madero	4,550	1,601	32
10	Durango		Pánuco de Coronado					
		20	Coronado	8	Francisco Javier Mina (Corralejo)	919	201	9
10	Durango		Pánuco de Coronado					
		20	Coronado	14	General Lázaro Cárdenas	389	121	27
10	Durango		Pánuco de Coronado					
		20	Coronado	9	Francisco Rueda Serrano	541	160	23

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

5.5 Topography, elevation, and vegetation

La Preciosa lies on the western edge of the high plains of northern México, an extensive volcanic plateau characterised by narrow, northwest trending ranges separated by wide, flat-floored filled basins. In the Durango area, the basins have elevations of between 1,900 m to 2,100 m above sea level and the higher peaks rise to 3,000 m. The Property elevation in the area of the mineralised zones at La Preciosa is between 1,990 m and 2,265 m. The highest elevations on the Property are at the northwest trending La Preciosa Ridge which overlies the La Gloria and Abundancia veins. A broad valley forms to the east of the ridge and extends approximately 1 km toward another lower lying ridge to the northeast. Grasses, small shrubs, and cactus comprise the typical vegetation on the steep hillsides with larger bushes and mesquite trees in the lower lying areas near springs and streams. Nearby farmers produce beans and maize with groundwater sourced from thick gravel beds in the surrounding plains. Local cattle graze on land dominated by litho-soils supporting nopal (prickly pear) and huizache (acacia) scrubland.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

6 History

6.1 Prior ownership, exploration, and development work

6.1.1 Late 19th century work

Mining has occurred on the Property area since the late 19th century. The earliest known workings from this time are concentrated on the Abundancia and La Gloria veins at the north end of La Preciosa Ridge, and are known as the Mina La Preciosa. Drifting on a vein at the south end of the ridges at Mina El Orito may also have taken place during the same time period. Mining ceased during the start of the Mexican Revolution in 1910 and the Property area lay idle until selective small scale mining operations took place between 1970 and 1979. Previous mining is believed to total no more than 30,000 t of material.

6.1.2 Work by Luismin from 1981 to 1982 and 1994

In 1981, Compañía Minera Minas San Luis (Luismin), operating as Minera Thesalia through a joint venture between Tormex S.A. and Luismin, conducted detailed channel sampling of surface outcrops in the eastern breccias (Zona Oriente) and main vein systems as well as a single east-west line of induced polarisation (IP) resistivity across the Property. Luismin also drilled seven diamond drill core holes, two from underground and five from surface, for 1319 m. The holes targeted the Abundancia and La Gloria veins 50 m to 75 m below the primary underground workings on the 2065 level. The drill programme terminated in 1982, reportedly due to falling metal prices. The half core is still intact and stored on site and the drillhole data is available in the database.

Luismin enlarged the main 2065 level within the Abundancia and La Gloria vein underground workings to a 3 m by 3 m size over approximately 60% of the drifts to provide access for trackless mining and drilling equipment. Luismin collected underground channel samples at two to three metre intervals along the drifts. In addition, Luismin collected chip samples from a total of 450 m of underground workings along the Abundancia vein and 408 m along the La Gloria vein. In total, Luismin collected 1,365 chip samples from underground.

Luismin extracted approximately 11,730 t of material at an estimated grade of 0.43 parts per million (ppm) gold (Au) and 157 ppm silver (Ag) from the underground workings and placed it in stockpiles at the portal, which remain largely intact.

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Luismin completed only limited work after 1982, including a single 313 m long drillhole in the eastern vein breccia system (Zona Oriente) in 1994. The drillhole intersected a series of variably silicified zones and veinlet stock work with anomalous silver, gold, lead, zinc, and mercury grades, but the hole did not pass through the entire width of the structure. In 1988 a small scale bench metallurgical test was performed on a sample of material extracted from the Abundancia and La Gloria veins, the results of this test work are discussed in Section 13.

Luismin staff prepared several historical internal mineral resource estimates which relied heavily on underground chip sample assays and only limited drilling. The results of these estimates are no longer relevant.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

6.1.3 Work by Orko from 2003 to 2008

In December 2003, Orko Gold Corp., now known as Orko Silver Corp., negotiated a joint-venture option agreement with Luismin. An independent property examination including the selection of eight surface rock samples for verification of historical data was performed in early 2004 on behalf of Orko. Geological mapping and surface sampling began in 2004 and target areas were identified for more detailed follow up.

In January 2005, 40 line kilometres of 3D induced polarisation resistivity and chargeability surveys were completed on the Property. The geophysical surveys were conducted over the north part of the main structures (Mina La Preciosa), extending across the central valley and the eastern vein breccia (Zona Oriente), and northward to Cerro Prieto and the northern projection of the main structures (La Preciosa Norte). Weak geophysical signatures were noted on the ridge where the Mina La Preciosa veins are known, but the method provided inconclusive results beneath the basalt cover to the north along the same vein trend. A large multi-line chargeability anomaly was observed in the central valley beneath the basaltic cover.

Orko's diamond drill core programme began in 2005 with the initial drilling targeting the Mina La Preciosa veins. The 2005 to 2008 drilling programmes successfully intersected the Abundancia, La Gloria, and Luz Elena veins in multiple intercepts, as well as oblique intercepts of the Esperancita and Carmen veins. The deeper and thicker Martha vein structure was discovered in late 2006 in drillhole BP06-77. In total, Orko drilled 388 diamond drill core holes for 152,368 m.

Orko prepared a series of five mineral resource estimates from 2006 to 2008. These estimates were prepared by interpretation of multiple mineralised zones defined by structure and by grade on longitudinal sections using minimum cut-off grades of 100 ppm Ag equivalent and 150 ppm Ag equivalent and a minimum true vein width of 1.5 m (silver equivalent was calculated as the silver assay grade plus 60 times the gold assay grade, assuming a 100% relative recovery of each metal). The interpretations were projected to a maximum of 25 m vertically below the drillhole intercept with the vein. Immersion method specific gravity measurements were available for every sample submitted during the 2005 to 2007 drilling programmes and were used to derive tonnes and contained metal. Grades were estimated by true thickness weighted average grade of all drill intercepts within each mineralised zone. All mineral resource estimates were classified as Inferred.

In March 2009, Orko disclosed the results of an independent mineral resource estimate undertaken by MDA (2009), based on Orko's 388 drillholes. Geological models were prepared on paper cross sections, digitised to honour the three dimensional contacts on the drillhole trace, and then converted into wireframe solids. The solids were used to code the assay database, define separate silver and gold grade estimation domains, to prepare the block model, and to code the block model for density. Silver grade estimation domains were based on a cut-off grade of approximately 4 ppm Ag to 30 ppm Ag, depending on the style of mineralisation. Gold grade estimation domains were based on a cut-off grade of approximately 0.1 ppm Au.

Drillhole intersections lying within the grade estimation domains were top cut for extreme grade values defined by examination of the sample grade statistics in each domain. Samples were then composited to 3 m lengths honouring geological boundaries. Estimation was by inverse distance squared with ordinary kriging and nearest neighbour estimates as a check, using a minimum of one sample composite and

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

a maximum of 12 composites required to return an estimate and a restriction of two composites per drillhole.

The percentage of the block lying within the wireframe was coded to the block model and the percentage was then used to calculate the weighted average of the tonnes and grades for mineral resource reporting. All high grade material estimated within or 10 m beyond the digitised historical workings was depleted from the model, resulting in the depletion of 410,000 t.

Mineral resources were classified as Inferred and Indicated and reported from vein material only above a range of silver equivalent cut-off grades using a ratio of 60 gold to 1 silver. Above a 100 ppm Ag equivalent, Indicated mineral resources were reported as 10.6 million tonnes (Mt) at 201 ppm Ag equivalent, 185 ppm Ag, and 0.27 ppm Au in the Indicated category and 12.1 Mt at 200 ppm Ag equivalent, 185 ppm Ag, and 0.25 ppm Au in the Inferred category. These mineral resource estimates have not been reviewed or validated by QG and are reported for historical purposes only. The results of these mineral resource estimates have been superseded by the updated mineral resource estimates presented in Section 14.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

7 Geological setting and mineralisation

Information in this section has been excerpted and updated from MDA (2009) and Coote (2010).

7.1 Regional geology

The Property is located in a geological sub-province known as the Altas Llanuras or High Plains, on the eastern flank of the Sierra Madre Occidental mountain range (Figure 7.1). The Altas Llanuras sub-province is a volcanic highland composed of Tertiary (Paleocene) to Quaternary (Pleistocene) age sequences of andesite, dacite-rhyolite, and basalt, which in turn rest on a basement of Cretaceous age conglomerate and Permian age metamorphic rocks. The present basin and range topography reflects a series of north to northwest trending linear grabens along the range fronts.

In the region north of the city of Durango, sedimentary rocks of Cretaceous age are exposed in small windows through the Tertiary age volcanic rock cover. These consist of mudstone, shale, limestone, and conglomerate with volcanic, sedimentary, and limestone clasts. The Cretaceous age rocks are covered by a sequence of andesite tuff, flows, and agglomerate of the Paleocene-Eocene age Lower Volcanic Series. In the surrounding ranges, the Lower Volcanic Series is overlain by thick sequences of rhyolite and dacite ignimbrite, tuff, and volcanic breccia of the Oligocene age Upper Volcanic Series. The Upper Volcanic Series is not exposed at La Preciosa, but it is exposed in cliffs to the west of La Preciosa.

The basins and parts of the lower hills are covered with varying thicknesses of Pliocene to Pleistocene age basalt that erupted from numerous vents now marked by small volcanic cones and domes that dot the plains. Several volcanic vents have been mapped on the Property, including the prominent Cerro Prieto.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 7.1 Regional geological setting map

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

7.2 Local geology

The oldest rocks within the Property, found only in deeper drill core intersections, are a Permian age metamorphic series consisting of graphitic schist, chlorite schist, and layers of quartzite. Above the metamorphic units is a thick package of Early Cretaceous age polymictic conglomerate composed of fragments of sub-angular to rounded schist, limestone, quartz, intrusives, and volcanic rocks and containing lenses of arkosic sandstone. This sedimentary package is overlain by andesitic tuff, andesite, and agglomerate of the regional Tertiary age Lower Volcanic Series. In places the flows are porphyritic and tuffs are partly welded. Rhyolites of the Tertiary age Upper Volcanic Series are not found in the immediate study area, but can be seen on cliffs further to the west on the San Juan property. The Cretaceous age conglomerate and Tertiary age Lower Volcanic Series andesitic rocks are the main host rocks of the mineralised veins, although vein mineralisation does extend into the basement metamorphic rocks. There are a few dacitic, rhyolitic, and andesitic dikes and micro-sills noted in deeper core intersections, but intrusive rocks are generally rare. The youngest rocks are basalt flows which erupted from several Pleistocene age volcanic vents and which now fill the lower valleys. A small number of basalt dykes related to this extrusive activity were encountered in drilling at La Preciosa. Cerro Prieto, Cerro Blanco, and Cerro La Chicharronera are prominent examples of the volcanic vents. An example cross section at 2701780 mN showing the drillhole traces and lithology at La Preciosa is shown in Figure 7.2.

Figure 7.2

Example cross section of drillholes and lithology at 2701780 mN

The Property covers a series of Tertiary age gold and silver-bearing epithermal quartz veins which also contain barite, calcite, fluorite, and quantities of base metals, primarily zinc, lead, and copper. There are two major vein and vein breccia systems exposed on a

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

series of hills and ridges which are separated by a flat-floored valley roughly 800 m in width. The main vein system on La Preciosa Ridge (shown in Figure 7.3) consists of dominantly northward-striking and westward-dipping veins (e.g., Abundancia, La Gloria, Esperancita, Luz Elena, and Martha), plus east-west striking, south-dipping cross-cutting veins (e.g., Transversal). The eastern vein breccia system (Martha East) strikes northwest and is interpreted to be a surface expression of the shallowly dipping Martha Vein. A sub-parallel north-northwest trending vein system (La Plomosa, El Vaquero, and Nancy) is exposed on the hills immediately to the west of La Preciosa Ridge, mostly on the San Juan concession.

Figure 7.3

Local geology plan

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

7.3 Property geology

The La Preciosa Ridge vein system has been traced on surface for over 3.7 km and drilling has revealed that the veins continue to the north beneath the basalt cover. Exploration towards the northwest of the Martha vein was not conclusive because the drillholes did not extend to the contact of the volcanics and conglomerate. It is possible that the Martha vein has been truncated by a normal, east-west trending fault with dextral displacement, moving the vein to the east and at greater depth. Future drill programmes with deeper holes will explore this possibility. The veins are also interpreted to extend farther south of known exposures.

Individual veins have been traced for up to 3.1 km along strike. Within the main vein system, the Abundancia, La Gloria, Luz Elena, and Martha veins have been explored in the most detail. A representative cross section at 2701780 m N showing the Gloria, Abundancia, Luz Elena, Pica, Alacran, and Martha veins, drillhole traces, and the principal rock groups is shown in Figure 7.4. The Abundancia and La Gloria veins coalesce at depth with a shallow northward plunge at the intersection and the merged vein continues as the Abundancia vein. Vein thicknesses vary from 1.5 m to 26 m wide at Abundancia, 1.5 m to 17 m at La Gloria, and 1.5 m to 35 m at Martha veins. Continuity of the Abundancia and La Gloria vein structures has been demonstrated through a total of 2.5 km of underground drifts.

The Martha vein contains the largest part of the mineral resource on the Property. Mineralisation is found in metamorphic rocks at depth, through to the conglomerate unit above, and then follows the angular unconformity at the base of the andesite. The portion of the Martha vein with the greatest widths and highest grades occurs when the low angle structure develops on the contact of the volcanic and conglomerate units. The vein continues to depth in the shales but usually splits into several narrow veins. A similar effect occurs where the vein develops between the contact between the volcanic rocks and schists, or else when the vein extends into the volcanic units.

The east-west trending Transversal veins occupy a south-dipping normal fault, with the Zona Sur area representing the short offset, down dropped block. The Abundancia vein continues south of the Transversal vein in the Zona Sur. As it is in a structurally separate sector, it has been interpreted apart from the main Abundancia vein. The Esperancita vein is a northwest trending structure overlying the Abundancia vein.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 7.4 **La Preciosa cross section at 2701780 mN showing drillhole traces, veins, and lithology**

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

7.4 Mineralisation

Mineralisation at the Property is hosted within multiple discrete poly-phase quartz veins, often displaying banded, smoky, drusy, and chalcedony textures. Fluorite, amethyst, a substantial number of barite laths, calcite, and rhodocrosite may also be present, and sulphide mineralisation in the form of sphalerite, galena, pyrite, chalcopryrite, acanthite, sparse native silver and free gold, as well as iron and manganese oxides have been noted in drill core. The principal silver bearing mineral at La Preciosa is acanthite, pseudomorphed after argentite or as microcrystalline to amorphous grains.

All veins on the deposit appear to be structurally controlled with movement on pre-, syn-, and post-mineralisation normal faults creating openings and fracturing in which the veins and mineralisation were deposited. The greatest thickness and highest grade portions are found where the largest amounts of opening and fracturing occurred. Away from these zones the expressions of the veins weaken. In each stage of variably crustiform banded fracture fill/breccia cement mineralogy, minor amounts of carbonate interstitial to quartz and chalcedonic quartz is succeeded by later carbonate-rich and quartz-poor assemblages. The trend of decreasing mosaic quartz/chalcedonic quartz and increasing carbonate/iron carbonate is repeated for each major stage of fracturing and brecciation.

In a recent petrologic study, Coote (2010) identified mainly argentite, tennantite/tetrahedrite, and Ag sulphosalts in samples. The majority of gold/electrum is inter-grown with or occupying the same paragenetic position as argentite, silver sulphosalts, sphalerite and galena, mostly transitional between quartz and carbonate/iron carbonate in formation. The minerals and textures identified in the studies indicate that gold/electrum has a similar hydrothermal paragenesis to silver sulphides/sulphosalts and base metal sulphides. Most of the identified gold/electrum is intergrown with argentite, silver sulphosalts, sphalerite, galena, and carbonate/iron carbonate. Only minor amounts of gold/electrum were identified in exclusive association with very fine grained quartz of early paragenesis in any given sequence of multiple stage fracture/cement mineralogy. There is a moderate to weak correlation between silver and gold, copper, and lead grades.

Wall rocks hosting mineralisation are variably silicified, with proximal patchy illite-smectite alteration and distal chlorite alteration. The presence of mangano-calcite has been noted in several drillholes, but it is not uniformly distributed. In shallower drillholes, pyrolusite and limonite often appear on fracture surfaces.

The host rocks and veins have undergone intense weathering. The base of oxidation is erratically distributed as weathering is controlled by the presence of post mineralisation faults which allowed the percolation of oxidised meteoric groundwater to vertical depths of 350 m below surface. Weathering minerals include iron oxides, iron carbonates, manganese oxides, and unidentified clays.

The Martha vein in general contains more calcite and a higher proportion of pale, low-iron content sphalerite, galena, and pyrite compared to the Abundancia and La Gloria veins. It can be considered as a mineralised zone or lode of stock work, silicification, breccias, veins, vein breccias, veinlets, and a general mix of multiple styles of mineralisation. Within this broader zone, the Martha lode ranges from 1 m thick to 35 m thick and averages approximately 5 m. Generally one but occasionally more high grade veins or vein breccias exist within the thickness of the vein zone. The high grade vein zones range from less than 1 m thick to 10 m thick and average 5 m. The upper

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Martha vein (Martha Superior) has the highest silver grades and is primarily composed of quartz and contains dark sphalerite, pyrite, chalcopyrite, argentite, silver sulphosalts, and native silver. The main Martha vein and the lower Martha vein (Martha Inferior) are lower in silver tenor and are composed primarily of quartz and carbonate (calcite and rhodochrosite) with pyrite, galena, iron-poor sphalerite, and silver sulphosalts. In Martha East, pale green fluorite is present as a late stage mineral at a surface expression of the Martha vein where it flares into veinlets and silicified breccia bodies.

Eighteen geologically continuous veins have been defined by extensive diamond drilling intersections and three dimensional geological interpretations (wireframes) have been made of these veins for the purpose of mineral resource estimation. The principal vein, Martha Alta, extends along strike for a distance of 3 km and has a width of approximately 1.5 km. All the vein sets strike roughly north-south except for two cross cutting veins (Transversal Norte and Transversal Sur). The dip of the individual veins varies, with some steeply dipping vein sets to the northwest close to surface, and others dipping shallowly, either close to the surface or at depth. There are three main sets of veins present at La Preciosa, including:

- Martha veins dipping at moderate angles (approximately 20° to 30°) towards the southwest (235° to 260°).
- Steeper dipping veins sitting above Martha (approximately 55° to 70° dip towards around 260°).
- Transverse veins (50° dip towards 170°).

Details of each of the defined veins, including volume, strike length, thickness, orientation, and depth below surface are given in Table 7.1.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 7.1 Vein volumes and orientations

Vein	Volume (m3)	Strike length (m)	Down dip width (m)	Thickness (m)	Dip	Strike	Depth below surface (m)
Carmen (2 lenses)	274,400	450	50 - 125	5	80	290	30 and 165
Gloria	743,600	900	200	4	80	350	0 to 50
Gloria Rama	162,300	380	160	3	60	350	0 to 50
Nieta	137,700	280	100	4	60	340	0
Pica (2 lenses)	543,600	900	200 - 400	2	60	350	50 and 100
				5-15 (average)			
Martha Alta	15,217,800	3,100	600 1,400	5)	20	320	0
Martha Baja	2,045,800	1,400	200 1,000	3	20	330	0
Martha Media	1,030,000	580	200	9	40	360	185
				5 10 (average)			
Martha Media Alta	187,700	290	120 180	5)	20	360	200
Martha Ramas (7 lenses)	978,100	2,150	100 220	2	10 30	360	30 to 300
Transversal Norte	242,600	500	150	2.5	45	075	0
Transversal Sur	423,700	650	150 400	3	50	090	0
Abundancia (2 lenses)	2,402,100	1,700	300 500	4	40	360	0
Alacran	244,000	500	250	2	30	350	60
Esperancita	165,600	450	200	2	45 70	330	0
Luz Elena (2 lenses)	237,300	550	300	2	30 and 65	350	50 and 150
Nueva	292,900	530	400	1.5	5	350	35
Olin	71,900	125	200	3	30	350	160
Sur	218,500	530	175 250	2	20	350	10

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

8 Deposit types

Information in this section is excerpted and updated from MDA (2009) and Coote (2010).

Mineralisation at the Property is hosted by quartz-carbonate-barite veins. The occurrence of adularia and the style of early quartz and chalcedonic quartz replacement amongst wall rock replacement and fracture-fill cement assemblages confirm that silver and base metal mineralisation is associated with low to intermediate sulphidation epithermal style systems typical of the Mexican silver belt.

Significant widths of mineralised quartz and carbonate dominated fracture fill and breccia cement assemblages have developed as a result of extended episodes of hydrothermal fluid flow and repeated rupturing of wall rock and pre-existing vein/cement assemblages. Multiple stages of silver and base metal mineralisation are associated with repeated fluid boiling and mixing events, defined by crustiform banded fill/cement assemblages.

The Martha vein, which contains the principal mineral resources at La Preciosa, is a low angle structure partly localised at the contact between sedimentary rocks (conglomerate and sandstone) and volcanic rocks (andesite/andesite clastic rocks).

The geology and style of mineralisation at La Preciosa are similar to those of other silver producing districts in the western Americas. México is host to many silver-gold mining districts, alternating with Peru as the largest silver producer in the world.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

9 Exploration

Information in this section is excerpted and updated from MDA (2009).

No significant exploration has been reported on the Property prior to 1981, when Luismin began working on the Property. Only limited exploration took place between 1982 and 2004, when Orko acquired the Property.

9.1 Exploration by Luismin from 1981 to 1982 and 1994

Luismin conducted exploration between 1981 and 1982, including detailed channel sampling of surface outcrops in the main vein systems and Zona Oriente (now believed to be a surface expression of the Martha vein), geophysical surveying of a single IP resistivity line across the north end of La Preciosa Ridge extending eastward to Zona Oriente, and diamond drilling of the Abundancia and La Gloria veins. There are no available details of the results of the geophysical programme although it is reported that a weak response was interpreted for the area of the Abundancia and La Gloria veins and a weaker response was interpreted on the silicified mounds of Zona Oriente. The low sulphide content and low contrast between quartz veins and enclosing silicified andesite could be attributed to the lack of a stronger geophysical response. The 1981 and 1982 drilling programme comprising 7 drillholes and the 1994 programme comprising a single drillhole were reportedly terminated due to falling metal prices. More details on the diamond drilling programme are given in Section 10.

Luismin enlarged approximately 60% of the drifts to 3 m high by 3 m wide on the main 2065 m level within the Abundancia and La Gloria vein underground workings to provide access for trackless mining and drilling equipment. Underground channel samples were selected at 2 m to 3 m intervals along the drifts. In addition, 450 m of underground workings along the Abundancia vein and 408 m along the La Gloria vein were chip sampled. In total, 1,365 chip samples were collected underground by Luismin and 406 channels are preserved in the current drilling database.

Luismin staff prepared several historical internal mineral resource estimates which relied heavily on underground chip sample assays and only limited drilling. The results of these estimates are no longer relevant.

9.2 Exploration by Orko from 2004 to 2008

In early 2004, Orko commissioned an independent property examination which included the collection of eight surface rock samples for verification of historic data. Later in 2004, the Property was mapped at a scale of 1:5000, identifying target areas for more detailed work.

In January 2005, SJ Geophysics Ltd. of Delta, BC, Canada conducted a three dimensional IP resistivity and chargeability geophysical survey. The survey took place over the north part of the main structures at Mina La Preciosa, extending across the central valley and the eastern vein-breccia (Zona Oriente) and northward to Cerro Prieto and the northern projection of the main structures. 40 line-kilometres were run at 100 m line spacing and 25 m station spacing. A weak geophysical signature was noted on the shallow, near surface response high on the ridge where veins are known, but the resistivity method was not successful beneath the basalt cover to the north. A large,

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

multi-line chargeability anomaly was delineated beneath the basaltic cover in the valley between La Preciosa Ridge and Zona Oriente.

A geochemical sampling programme was conducted over the southern part of La Preciosa in 2008, with the grid starting on Cerro El Venado and heading southward on east-west lines. On the ridges the line spacing was 100 m and the sampling spacing was 25 m along lines, and in flat-lying areas, the sample spacing was 50 m. The entire grid runs 5 km north-south and averages 2 km wide east-west. 1,167 soil samples were collected from the B soil horizon. Strong multi-element geochemical anomalies were found for the Veta Nueva, El Orito, El Orito Norte, and Nancy veins.

Diamond drilling by Orko commenced in March 2005 on La Preciosa Ridge, targeting the Abundancia and La Gloria veins and intersecting the Luz Elena vein at depth. Other holes drilled during 2005 targeted the Zona Oriente area located 1 km northeast of the La Preciosa Ridge historic mine areas. The 2006 drilling campaign demonstrated continuity of vein mineralisation at La Preciosa Ridge from the south at Abundancia and to the north at Esperancita. Drilling also intersected the up dip portions of the Luz Elena vein to the east. The Martha vein was discovered in drillhole BP06-77 during late 2006 and later drilling in 2007 targeted both the shallow La Preciosa veins and the deeper Martha vein. The Martha vein was the primary target for the mid to late 2007 drill campaign, which extended the limits of the vein to the south and further up dip to the east. Also during 2007, Orko re-entered and extended several holes drilled in 2006 which were completed just above the projected Martha vein depth. By this time, the Martha vein had been expanded to cover an area of 2,000 m in the north-south direction and 1,600 m in the east-west direction, remaining open to the south and west. The northern extension has not been found and the eastern end outcrops or else abuts the recent basalt. In 2008 the principal drilling target was the up dip eastward side of Martha as well as along strike to the south-southeast.

After compiling the drilling data from each drilling campaign, Orko prepared a series of five mineral resource estimates from 2006 to 2008. The results of these mineral resource estimates have been superseded by the updated mineral resource estimates presented in Section 14.

9.3 Exploration by Pan American from 2009 to 2010

Since Pan American commenced operating the La Preciosa Project, exploration efforts concentrated on drilling 331 drillholes, mainly as infill drillholes to the north of the deposit. Details of this drilling programme are given in Section 10. The database as of 25 October 2010 comprised 726 drillholes for 238,864 m and was used to prepare the updated mineral resource estimates given in Section 14.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

10 Drilling

Information in this section has been updated from MDA (2009).

10.1 Drilling summary and database

All drill holes on the Property have been diamond core, of varying diameters, and drilled by Luismin, Orko, or Pan American. The database as of 25 October 2010 comprised 726 drillholes for 238,864 m. Most holes are oriented from west to east at varying dips, depending on the target vein orientation, to optimise the drillhole intersection with the vein, and therefore the down hole length of the drill intersection is close to the true thickness of the vein. The mineral resource estimation methodology is not sensitive to intersection angle.

Holes have been drilled over targets for a combined strike distance of over 9 km, and the majority of the drillholes on the Property have been used for geological interpretation and estimation of Inferred and Indicated mineral resources at La Preciosa, covering an area of 3 km by 2 km.

Table 10.1 shows details of the drillhole database (as well as the channel samples) by operator and by prospect as at 25 October 2010. A location plan of the drillholes by operator available in the database as at 25 October 2010 relative to the lease boundaries and the mineral resource area is shown in Figure 10.1. A representative cross section at 2701980mN showing the orientation of drillholes relative to the dip of the veins is given in Figure 10.2.

Table 10.1 La Preciosa Property drillhole and channel database

Operator	Prospect	Years		# holes /channels	Metres	Hole number prefix
		1981	1982 and 1994			
Luismin	La Preciosa	1981	1982 and 1994	7	1,319	BP
Luismin	La Preciosa channel samples	1981 - 1982		406	867	CG, CGV, CA, CAV
Orko	Orito	2006		7	2,326	BO
Orko	San Juan	2007		8	3,556	SJ
Orko	La Preciosa	2006		1	451	BC
Orko	La Preciosa	2005		6	1,910	BB
Orko	La Preciosa	2005 to 2008		366	144,125	BP05 to BP08
Pan American	La Preciosa	2009 to 2010		331	85,177	BP09 to BP10
Total				1,132	239,733	

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 10.1 **Location map of drillholes relative to mineral resource area**

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 10.2

Cross section at 2701980 showing drillhole orientation relative to vein orientations

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

10.2 Drilling by Luismin from 1981 to 1982 and 1994

There are currently 7 drillholes for 1,319 m in the La Preciosa database. Two holes were drilled from underground and five were drilled from the surface. The primary targets were the Abundancia and La Gloria veins at 50 m to 75 m below the primary underground workings on the 2065 level. A final hole 313 m in length was drilled in 1994 in the eastern vein breccia system, but the data for the drillhole is not in the database. The hole reportedly intersected a series of variably silicified zones and veinlet stock work with elevated silver, gold, lead, zinc, and mercury values, but did not completely intersect the structure. There are no available details on the drilling procedures, except that the drill core was either of BQ or AX size. The remaining half core is stored in the original core boxes on site.

10.3 Drilling by Orko from 2005 to 2008

Orko began drilling on the Property in March 2005, ultimately completing 388 diamond drillholes for 152,368 m, spaced on roughly 100 m centres and with all but 16 of the holes targeting various veins at La Preciosa. Orko contracted Major Drilling International for all of the drilling completed on the Project, using Longyear 44, 38A, and 38B machines. Drill core diameter started at HQ size with reduction to NQ size at around 260 m down the hole. Between rod runs, the drillers inserted a wooden block marked with the down hole depth in both feet and metres. Downhole surveys were taken approximately every 50 m down the hole with a Reflex survey instrument, and the results of the surveys indicate moderate deviation in bearing and dip down the hole. No down hole survey is available at the collar of the drillhole.

Drill core was collected on a daily basis from the drill rig by Orko technicians, who taped the boxes shut prior to transport to the site core shed. Once at the shed, the technicians cleaned the boxes and core, and marked the boxes with the hole number, box number, and the depth intervals, and reconciled them with the depths marked on the driller's depth blocks.

After the drillhole was completed, a PVC pipe was placed in the hole and a cement block was installed on the collar. The cement block was clearly inscribed with the name of the drillhole, the final hole length, and the bearing and dip of the hole. An independent surveyor was contracted to survey the coordinates of the collar on a regular basis.

10.4 Drilling by Pan American from 2009 to 2010

Pan American began drilling on the Property in June, 2009 and as at 25 October 2010 had completed 331 diamond drillholes for 85,177 m. The drilling focussed on infilling the 100 m centres completed by Orko to 50 m centres over an approximately 800 square metre (m²) area located to the north and northwest of the deposit. Additionally, confirmatory infill holes were drilled on section elsewhere over the mineral resource, as well as two 15 m to 20 m close-spaced drill crosses to assess the short range continuity of geology and mineralisation. The same drilling contractor employed by Orko, Major Drilling International, was engaged by Pan American to carry out the drilling programme and similar

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

drilling and down hole surveying procedures were followed, although greater capacity drill rigs were employed which resulted in fewer NQ sized drillholes. From early 2010 selected drillholes were surveyed using a Reflex ACT/QPQ orientation tool to obtain oriented drill core for geotechnical

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

purposes. The preservation of the drill collar and survey of the collar coordinates follow the same procedure established by Orko.

10.5 Exploration targets

In addition to extending the mineralisation limits of the known veins, there are a number of other smaller and lower priority exploration targets located outside of the area of the deposits comprising the mineral resource. Three of these targets, including the Nancy, El Orito Norte, and Mina El Orito veins, have been tested by diamond drillholes while the remaining targets have been identified by surface mapping and anomalous soil geochemistry results. A plan of these target areas is shown in Figure 10.3 and a summary of the drilling results is given in Table 10.2.

The Nancy vein is a structure located in the Western Structural Trend located about 1.4 km to the southwest of the Martha vein. The initial discovery of the surface outcrop of a 3 m wide northern extension of the vein was made by Orko in 2006. The target was followed up with soil and trench sampling which yielded anomalously high silver values. In 2010 Pan American drilled 12 holes spaced on a 100 m by 100 m grid. Eleven of these holes intersected a continuous flat lying vein with a strike length of 300 m and a width of 200 m at between 50 m and 100 m below the surface.

El Orito Norte is a continuation of a vein interpreted to connect Mina El Orito in the south to Veta Nueva in the north, and was discovered by Orko in 2004. The vein is located about 250 m to the southwest of the Martha vein. In 2011 Pan American drilled 11 holes on a roughly 100 m by 100 m grid spacing and intersected a moderately dipping vein (approximately 60°) located between 175 m and 275 m below surface in ten of the drillholes.

Mina El Orito is located at the southern end of the main structural trend and dates from before the Mexican Revolution. The old workings are not accessible but rock piles and a series of shafts can be traced over a strike length of approximately 500 m. In 2006 Orko drilled six holes on a 100 m by 100 m grid spacing, but no spatially continuous anomalous metal values have yet been intersected. The best drillhole, BO06-01, intersected anomalous metal values of 43 ppm Ag and 63.7 ppm Au over a down hole interval of 0.60 m.

Other targets identified by surface mapping and soil geochemistry include Veta Nueva, Nancy Sur, La Plomosa Sur, and Dany. Veta Nueva, located south of Cerro El Venado on La Preciosa Ridge in the Zona Sur area, was discovered by Luismin in the 1980s and is exposed in the north wall of a steep valley cut which separates Zona Sur from El Orito Norte. Nancy Sur is located 350 m to the southeast of the Nancy vein and is interpreted to be a southern extension of the Nancy vein. La Plomosa Sur is located to the west on the ridge above the Nancy vein in the Western Structural Trend. A very old open pit is present at the top of the ridge. Dany is located south of the La Plomosa Sur area.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 10.3 **Plan of exploration targets**

Table 10.2 **Downhole intersection results from exploration targets**

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Target	Hole number	Downhole length (m)(1)	Ag (ppm)	Au (ppm)
Nancy	BP10-588	0.90	91	0.12
	BP10-590	0.35	254	0.03
	BP10-592	6.70	67	0.08
	BP10-593	3.30	42	0.18
	BP10-595	2.50	157	1.12
	BP10-597	3.40	34	0.06
	BP10-601	0.80	104	1.46
	BP10-602	1.40	34	0.10

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Target	Hole number	Downhole length (m)(1)	Ag (ppm)	Au (ppm)
	BP10-604	0.95	100	0.14
	BP10-606	1.50	41	0.17
	BP10-608	1.10	36	0.08
El Orito Norte	BP10-562	1.30	20	0.03
	BP10-568	2.05	2	0.02
	BP10-576	2.30	142	0.02
	BP10-584	14.30	69	0.02
	BP10-591	0.30	35	0.04
	BP10-594	0.40	12	0.05
	BP10-598	6.35	168	0.12
	BP10-603	1.15	149	0.09
	BP10-612	1.70	29	0.06
	BP10-614	8.20	84	0.11

Note(1): The down hole length is not equal to the true width of the intersection, which varies depending upon the orientation of the drillhole as it intersects the mineralised zone. Holes are planned to intersect the zones as close to perpendicular as possible, so the true width may be approximately 5% narrower than the down hole length.

10.6 Material impact on accuracy and reliability of drilling results

MDA (2009) examined core recovery of Orko drillholes in detail and QG examined all drillholes available as at 25 October 2010. Both MDA and QG determined that core recovery is generally poorer in mineralised lithologies, but that within mineralised material, there is no obvious or strong correlation between recovery and silver grades.

Both Orko and Pan American use the same methodology for recording core recovery. Between each drill rod run, the diamond drillers insert a block in the core tray indicating the down hole depth of the drill rods. The difference in the down hole depths between two consecutive depth blocks gives the length of each drill run and depending on ground conditions, the length of each drill run may not always be equal to the full length of the drill rod. Geological technicians determine core recovery by measuring the total length of recovered core in the core tray between the drill runs and dividing by the length of each drill run.

Measuring drill core recovery between drill runs is problematic when sample intervals do not coincide with the drill run depths. Usually sample intervals are selected with respect to geological boundaries and are usually selected at intervals less than the length of the drill run. This results in a repetition of the core recovery measurement between consecutive samples and prevents knowing exactly over which assay interval any core loss occurred. The number of these repetitions is relatively small, but to eliminate the problem entirely, measuring drill core recovery on a sample by sample basis is recommended for future drilling campaigns to better assess whether there is any correlation between sample recovery and silver grade.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

The lowest sample recovery of 86% occurs in vein lithologies. There is no way to determine how the core loss occurred for each drill run, but it can occur due to broken ground conditions, the presence of voids within the rock mass, or poor drilling practices.

10.7 Conclusions and recommendations

No special measures were taken to improve drill core recovery except changing the amount of additives such as polymers and drilling mud and occasionally drilling shorter runs when the geologist was present at the rigs. Considering that drill core recovery averages approximately 86% in vein material, and that this 14% loss of material is one of the major factors affecting confidence in the mineral resource estimates, more care should be placed on improving drill core recovery within the vein systems, perhaps with the use of triple tube drilling methods.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

11 Sample preparation, analyses, and security

Information in this section is excerpted and updated from MDA (2009) and Snowden (2011).

11.1 Sampling by Luismin from 1981 to 1982 and 1994

There are no documented details on the sampling methodology, approach, and security measures employed by Luismin. The only detail known from visual inspection of the drill core is that samples were split with a screw-wedge core splitter and that the drill core was clearly marked and neatly stored. The number of samples selected and assayed by Luismin, approximately 130 samples, comprises a very small proportion of the database. The lengths of these samples are variable and were probably selected according to geological features, with the majority of the samples ranging from 0.5 to 2.0 m in length. The only known detail about the laboratory sample preparation and analytical methods undertaken by Luismin is that the samples were sent to the Luismin laboratory in Durango.

11.2 Sampling by Orko from 2005 to 2008

11.2.1 Sample preparation and security

Orko technicians collected the core trays from the drill rig on a daily basis. Once at the shed, the technicians cleaned the boxes and core, and marked the boxes with the hole number, box number, and the depth intervals, and reconciled them with the depths marked on the drillers depth blocks. For each drill rod run, the technicians recorded core recovery as a percentage between 0 and 100%. The technicians also recorded a variation of the rock quality designation (RQD which is a measure of the unbroken drill core segments in lengths of 10 centimetres (cm) or greater, recorded as a percentage between 0 and 100%) for each drill rod run, by measuring the unbroken drill core segments in lengths of 15 cm and 20 cm. Each core tray was then photographed.

Once the geologist was ready to log the hole, the drill core was laid out on racks for logging and the geologist recorded the lithological description, a graphic lithology/structural log, alteration and mineralisation type and strength, structural notes, sample numbers, sample depth intervals, oxidation and sulphide percentages, and codes for rock type, structure, and vein code by hand on paper logging sheets.

Once the logging was complete, the geologist marked the sample intervals on the drill core with respect to geological features and marked a cutting line on the long axis of the drill core. The sample interval and the corresponding sample number were also marked on the ribs of the core

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

box in permanent marker for later reference. The majority of sample lengths are between 20 cm and 3 m and within the higher grade zones, sample lengths are typically between 20 cm and 2 m. The core was sawn in half by an Orko technician using a diamond bladed saw, following the line marked on the core by the geologist. After cutting, one half of the sample was placed in a plastic sample bag with a sample tag printed with the corresponding sample number and the remaining half was placed back in the drill core tray.

After sampling, the boxes with the remaining half drill core were stored on numbered racks in a large, well lit, and secure core shed where they currently remain. The samples in the plastic sample bags were then allowed to air dry, then measured for density,

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

returned to the plastic sample bag, and placed in a large rice bag. The weight of each rice bag was recorded and the bag was driven by Orko personnel to the sample preparation facility.

From 2005 to 2007, most of the first approximately 100 drillholes (up to BP07-093) were prepared by the primary commercial laboratory, SGS Minerals Services (SGS) in Durango, or else at the secondary commercial laboratory, Inspectorate America Corporation (Inspectorate), also in Durango. After the first 100 drillholes, the primary laboratory was switched to Inspectorate in an attempt to increase sample assay turn-around times. The majority of the samples were prepared by Inspectorate. Check assays were sent to Inspectorate, SGS, and ALS Chemex in North Vancouver, BC, Canada, or in Reno, Nevada, USA.

Neither the Inspectorate or SGS sample preparation laboratories in Durango have been certified by any standards association, but SGS's analytical laboratory in Toronto, Canada has been accredited with ISO/IEC 17025 and Inspectorate's analytical laboratory in Reno, Nevada, USA, is ISO 9001:2008 certified.

11.2.2 Analytical methods

At the preparation laboratory, samples were numerically ordered, crushed, and a sub-sample was taken for pulverisation. The remaining crushed sample was returned to its plastic bag and placed in its sack. This portion, known as the coarse reject, was picked up from the preparation laboratory and returned to the Property site for safe-keeping. The pulp from the pulverisation process was placed in a paper packet and boxed for shipment to the SGS analytical laboratory in Toronto or else to Inspectorate in Reno. A summary of the analytical techniques used to assay Orko's samples is given in Table 11.1. The differences in the assay techniques and the resulting lower and upper limit thresholds shown in Table 11.1 may result in differences in grades obtained by the various laboratories. For example, a four acid digest may result in higher assay values at lower grade ranges when compared to a three acid digest method, but may not show any marked difference at higher grades (such as above 300 ppm Ag).

Table 11.1 Summary of analytical techniques used to assay Orko's samples

Laboratory	Element	Analytical method	Lower upper limit (ppm)
SGS	Au < 10 ppm	FA-AAS	0.005 10
	Au > 10 ppm	FA-GRAV	>3
	Ag <300 ppm	3 acid digest with AAS finish	0.3 - 300
	Ag > 300 ppm	FA-GRAV	>300
Inspectorate	Au	FA-GRAV	> 3
	Ag < 200 ppm	4 acid digest with ICP finish	0.1 200
	Ag > 200 ppm	FA-GRAV	> 200
ALS Chemex	Au < 10 ppm	FA-AAS	0.005 10

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Au > 10 ppm	FA-GRAV	0.05	1,000
Ag	FA-GRAV	5	10,000

Note: FA is fire assay, AAS is atomic absorption spectrometry, GRAV is gravimetric finish, ICP is inductively coupled plasma.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

All samples were also run through an inductively coupled plasma (ICP) analysis for 40 element spectral determination after a strong acid digest. This method reports values well for elements in minerals which are digestible in the acid, however, mineral resistant to the acid may give only partial values. Oxides, sulphides, and carbonates yield full digestion and thus the base metal values are accurate. Silver has a 10 ppm upper detection limit and is thus not used for the Project where significant numbers of sample grades exceed this value. The base metals Pb and Zn have an upper threshold of greater than 10,000 ppm (1%) and only those exceeding 1% require analysis by alternate methods.

11.2.3 QAQC

Orko systematically inserted QAQC samples into the sample stream throughout their drilling programmes, including blanks and standards. Generally every tenth samples comprised a standard or a blank sample. Duplicates were not included in the sample stream but were submitted in separate batches to an alternate laboratory as a check on laboratory bias.

Blanks

Standard industry practice is to submit blank samples which comprise a full volume material known to be free of mineralisation relevant to the deposit at grade levels well below the detection limit of the analytical machine. Blanks are used to detect sample switching and contamination during crushing, pulverising, and analysis, and should be submitted at a frequency of one for every 20 geological samples, with preference placed within the mineralised zones. A blank sample is considered to have failed and the sample batch may be considered contaminated if the assay result is greater than ten times the detection limit of the analytical machine.

Orko manufactured a number of blank samples from basalt drill core and from basalt boulders found in nearby fields. The blanks used on the Project were named Orko-2, Orko-4, Orko-5, Orko-7, and Orko-9. Silver data from 1,030 Orko-2 samples submitted to SGS and silver and gold data for 97 blank basalt drill core submitted to Inspectorate are present in the database. One blank was submitted as every 20th sample.

4% of the Orko-2 blank samples and 10% of the basalt drill core samples exceeded the practical detection limit for silver. None of the basalt drill core samples exceeded the practical detection limit for gold. Smith (2010) notes that the blank samples were not considered completely blank. As such it is not possible to determine whether the failed samples are a result of contamination or background silver grade in the blank samples, and therefore the blanks are unreliable for assessing whether contamination is an issue in the sample preparation and analytical laboratories. However, the magnitude of the failures indicates that there is no significant concern with sample contamination.

Standards

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Standard industry practice is to submit certified standards, which comprise material collected either from site or purchased from a commercial laboratory. The material is prepared by a laboratory and sent to an appropriate number of round robin laboratories who conduct a sufficient number of analyses, using consistent sample preparation and analytical techniques (and consistent with the methods intended for processing the site samples) to certify the sample grade within known error limits. Standards are used to assess the accuracy of sample grades and should be submitted at a frequency of one for every 20 geological samples, with preference placed within the mineralised zones. Standards should be submitted at all relevant grades, for all economic elements reported

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

in the mineral resource, including the cut-off, low, average, and high grades. Standard samples should be monitored on a real time basis, plotted on a chart over time, and assessed for bias and failure. A standard sample is considered to have failed if the assay value is greater than or less than three standard deviations of the certified value.

Orko primarily used standards prepared by SGS from material obtained at the Project site, named Orko-1, Orko-3, Orko-6, and Orko-8. The accepted values and standard deviations for the Orko standards for gold and silver are shown in Table 11.2.

The standards were problematic because they were not certified, record keeping is reported to have been inadequate and therefore the identity of the standards was not always certain (MDA, 2009), the standard deviation of some of the standards are unusually high (such as silver for Orko-1 and gold for all standards), and some of the accepted values are very similar to other standards. Therefore it is unclear whether any observed inaccuracies are due to inconsistencies in the standard itself, mislabelling of the standard during sample submission, or errors in the assay procedure.

A plot of the standard results on the same set of axes colour coded according to the assigned standard name shown in Figure 11.1 suggests that there may be some incorrect standard labelling, especially for some of the Orko-3 silver results and possibly for some of the Orko-8 silver results. Mislabelling of gold standards appears to be evident however the failed results are not mirrored in the silver results. As a result of the similarity between the acceptable limits for Orko-6 and Orko-3, it is not clear if sample mislabelling has occurred.

A total of 3,994 Orko standards were inserted into the sampling stream for a 4.5% insertion rate.

Table 11.2 Details of the standards used by Orko

Standard name	Au		Ag	
	Accepted value (ppm)	Standard deviation (ppm)	Accepted value (ppm)	Standard deviation (ppm)
Orko-1	0.210	0.0217	293.40	11.31
Orko-3	0.068	0.010	112.00	6.60
Orko-6	0.072	0.009	146.10	11.10
Orko-8	0.134	0.030	237.90	14.98

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 11.1 **Graphs of all Orko standards for silver and gold**

Orko-1 standard

A total of 564 Orko-1 standards were assayed during the Orko drilling programme and the results are shown in Figure 11.2. 99% of the gold values are within acceptable limits and bias is insignificant. The mean obtained for silver from the standard results is

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

278 ppm Ag which is significantly lower than the expected mean value of 293 ppm Ag, however, 94% of the silver values are within the acceptable limits. If the accepted silver value for this standard has been correctly defined, then the assay results associated with this standard may be considered conservatively low.

Figure 11.2 Graphs of the Orko-1 standard results for silver and gold

Orko-3 standard

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Orko-3 standards were submitted for analysis to both Inspectorate and SGS. The results from Inspectorate are shown in Figure 11.3 and from SGS in Figure 11.4. 851 Orko-3 standards were submitted to Inspectorate while 95 were submitted to SGS. 99% of the values from both laboratories plot within the acceptable limit of the certified value for gold.

96% of the silver values by Inspectorate and 99% of the silver values by SGS are within the acceptable limits. No bias is noted in the Inspectorate data while a consistent bias in the SGS data is noted towards lower values than those expected from the certified data.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Figure 11.3 **Graphs of the Orko-3 standard results for silver and gold by Inspectorate**

Figure 11.4 **Graphs of the Orko-3 standard results for silver and gold by SGS**

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Orko-6 standard

1,382 Orko-6 standards were assayed during the Orko drilling programme and the results are shown in Figure 11.5. All of the gold values plot within the acceptable limits of the certified value for gold and 99% of the values plot within the acceptable limits of the certified value for silver.

Figure 11.5 **Graphs of the Orko-6 standard results for silver and gold**

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Orko-8 standard

1,102 Orko-8 standards were used in the Orko drilling programme and the results are shown in Figure 11.6. Nearly all of the gold data falls within the acceptable limits of the certified value and no bias in the results is evident.

Nearly all of the silver data falls within acceptable limits of the certified value. A significant bias is evident in the silver results with results from early batches plotting above the acceptable limits of the certified value and later batches plotting below the certified value.

Figure 11.6 Graphs of the Orko-8 standard results for silver and gold

Duplicates

Submitting duplicate samples, comprising either field duplicates (half drill core), coarse rejects, or pulp duplicates to the primary laboratory allows for assessment of the errors introduced during sample preparation and analysis and also provides an indication of the nugget effect or inherent variability in sample grades at very close distances. Sampling duplicate samples to an alternate laboratory allows for assessment of error and bias between laboratories, but it is impossible to know whether any differences in duplicate grades are attributable to error or bias. In order to make meaningful comparisons of original and the duplicate sample grades, both the primary and check laboratory must use consistent sample preparation and analytical techniques. Standard industry practice is to submit duplicate samples on the order of one for every 20 geological samples, or 5%.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Given the fine grain size and relatively small reduction in volume during sampling, pulp duplicates are expected to have good precision, while the coarser grain size of coarse rejects is expected to result in less precise values. Plotting the duplicate data on a quantile-quantile (Q-Q) can be used to demonstrate sample grade precision and any biases in the sample grades.

Several stages of duplicate analysis were undertaken by Orko and these are tabulated in Table 11.3. A total of 1,104 duplicates or 1% of total samples has been submitted for the Orko drillholes. The duplicates comprise both coarse reject and pulp duplicates. The duplicate sampling programmes are problematic in that the analytical technique (and therefore the upper and lower grade limit thresholds) used by the check laboratory was not always consistent with the analytical technique used by the primary laboratory, and therefore differences in the grades will be expected. For duplicates submitted to the same laboratory as the primary laboratory for both Inspectorate and SGS samples, good precision and no bias is noted.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 11.3 Details of duplicate analyses of Orko drill core samples

Description	Number of duplicates reported	Number of duplicates in database	Type	Primary Lab	Secondary Lab	Comments
Orko duplicates	331	317	Pulp	Inspectorate	ALS Chemex	Samples from five drillholes. Orko holes only.
3 Lab comparison	134 (per lab)	120 (per lab)	Coarse Reject (SGS) Pulp (ALS Chemex)	Inspectorate	SGS, ALS Chemex	All samples from drillhole BP07-102.
MDA pulps	240	236	Pulp	SGS, Inspectorate	ALS Chemex	Suite of samples from each mineralised vein Orko holes only.
MDA coarse rejects	267	267	Coarse Reject	SGS, Inspectorate	IAC	As above using the same sample numbers as the MDA pulps Orko holes only.
Martha		146	Pulp	SGS, Inspectorate	SGS	All samples from Martha vein only. Pan American and Orko holes. Done because of problems in correlating mineralisation over short distances between Orko and Pan American holes.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Orko duplicates

Orko submitted 331 pulp duplicates to ALS Chemex in North Vancouver, BC, Canada as a check on the original assay results provided by Inspectorate. Results for 317 of the pulp duplicates are available in the database. Of these assays, 79 samples were analysed for silver using the same technique at both laboratories (fire assay with gravimetric finish for samples greater than 200 ppm Ag). Samples less than 200 ppm Ag were analysed by a four acid digest with ICP finish at Inspectorate and samples less than 300 ppm Ag were analysed by three acid digest with atomic absorption spectrometry (AAS) finish at SGS. Assessment of the silver results on a Q-Q plot show a bias towards higher grades for the Inspectorate results for grades less than approximately 30 ppm Ag and a good correlation greater than 30 ppm Ag. Gold was analysed by fire assay with gravimetric finish at Inspectorate and by fire assay with AAS finish at SGS. Analysis of the 317 gold data on the Q-Q plot shows the results to be within acceptable limits with a bias towards higher values in the Inspectorate results. The Q-Q plots for silver and gold assays of the pulp duplicates are shown in Figure 11.7.

Figure 11.7 **Q-Q plots comparing silver and gold assays of pulp duplicates from Inspectorate and ALS Chemex**

September 2011

74

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Three laboratory comparison

A comparison of the assay results obtained from the three laboratories used throughout the Orko drilling programme was carried out. 134 samples from drillhole BP07-102 initially analysed by Inspectorate were submitted to SGS and ALS Chemex of North Vancouver, BC, Canada. SGS analysed a coarse reject duplicate while ALS Chemex analysed a pulp duplicate from the same sample. Results from 120 duplicates are available for the two laboratories.

Q-Q plots of the results between Inspectorate and SGS show a very good correlation between the duplicate and the primary analyses with no bias noted between the results for either silver or gold.

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Analysis of the results between Inspectorate and ALS Chemex on a Q-Q plots for silver and gold show the data to be within acceptable limits for both silver and gold with no significant bias for gold and a trend towards higher values in the Inspectorate data at higher silver grades.

MDA pulp duplicates

MDA (2009) completed duplicate analysis of samples from each of the mineralised vein intercepts to increase confidence in the Orko analytical data. Samples were originally analysed at SGS and Inspectorate and were sent to ALS Chemex in Reno for analysis. A total of 240 pulp samples, 179 from Inspectorate and 61 from SGS, were submitted for re-analysis. MDA inserted blanks and standards obtained from WCM Minerals in British Columbia into the sample stream. Two of the ten blanks reported failures for

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

gold but none failed for silver, and all of the standards performed within the accepted limits.

Analysis of the silver results between Inspectorate and ALS Chemex on a Q-Q plot shows a good correlation between the duplicate and the primary analyses with little bias between the two laboratories. The Q-Q plot for gold shows a good correlation for values greater than 0.20 ppm Au and a bias to higher values from ALS Chemex for grades less than 0.20 ppm Au.

Analysis of the silver results between SGS and ALS Chemex on a Q-Q plot shows a reasonable correlation between the duplicate and primary silver and gold analyses. No significant bias is present in either the silver or assay results.

MDA coarse reject duplicates

MDA (2009) submitted 267 coarse reject duplicates from the same list of samples as used for the three laboratories to Inspectorate to ascertain if there were any errors introduced during crushing and pulverising. Of the samples submitted, 192 were originally assayed at Inspectorate and 75 were originally assayed at SGS.

Q-Q plots of the original and duplicate Inspectorate results show a very good correlation between the duplicates and the primary analysis with no significant bias between the results for either silver or gold.

A Q-Q plot of the original SGS silver results and the Inspectorate duplicates shows a slight bias towards higher values obtained in the Inspectorate results between grades of approximately 50 ppm Ag and 200 ppm Ag. The bias could be due to the fact that SGS used a three acid digest for samples less than 200 ppm Ag while Inspectorate used a four acid digest for samples less than 200 ppm Ag. The Q-Q plot for gold shows a good correlation and insignificant bias between the results.

Martha duplicates

The results of the duplicate sampling of Orko's original samples by Pan American are discussed in the following section.

11.3 Sampling by Pan American from 2009 to 2010

11.3.1 Sample preparation and security

The drillhole logging and sampling methodology by Pan American follows much the same protocol developed by Orko. From drillhole BP10-458, RQD was measured on 10 cm intervals only.

The geologists determined the sample positions on the diamond drill core and marked the positions on the core and the core tray. The core was taken to the core cutting area and the trays were stacked until they were ready to be cut. The core was cut along the line defined by the geologist with a water cooled diamond bladed saw. After each piece of core was cut in half, both pieces were replaced in the core boxes.

Once the core was sawn in half, the boxes were taken to the sampling area where sample bags and sample tags were labelled and consecutive sample numbers were assigned to the sample intervals. Every tenth sample number is assigned to a standard or blank sample. Every 50th samples is duplicated. Duplicate splits from pulverised samples are taken from every sample number ending with 49 or 99. The duplicate pulp sample is separately bagged and given the next sample identification number (i.e., duplicate sample numbers end with 50 or 00). The pieces of half core to be assayed

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

were placed in labelled sample bags along with the corresponding sample ticket, and then into labelled rice bags along with the labelled standard and blank samples. Ten samples were placed in each rice bag. The filled rice bags were stored on site until a few drillholes were ready to be sent out as one consignment to the SGS laboratory in Durango. The core samples are driven directly to the SGS laboratory in Durango by a Pan American employee.

11.3.2 Analytical methods

All Pan American samples, with the exception of the pulp duplicates, are prepared and assayed by SGS Laboratories in Durango, México. Pulp duplicate samples are analysed at Inspectorate in Sparks, Nevada.

At the SGS laboratory, the samples are set out in numerical order, individually crushed, then riffle split to provide a sub-sample for pulverising. The crushed material left over after the sub-sample has been removed (the coarse reject) is returned to the labelled plastic bag from which it was taken, sealed, and eventually returned to Pan American for storage at the La Preciosa site. The sub-sample is pulverised and approximately 200 g is placed in a small labelled paper packet. After the required assay aliquots have been removed, the residual material remaining in the packet is also returned to Pan American for storage on site at La Preciosa.

A summary of the analytical techniques and tolerances used by SGS and Inspectorate is shown in Table 11.4.

Table 11.4 Details of the analytical techniques used to assay Pan American s samples

Laboratory	Element	Analytical method	Lower - upper limit (ppm)
SGS	Ag < 300 ppm	Three acid digest with AAS finish	0.3 - 300
	Ag > 300 ppm	Fire assay with gravimetric finish	> 5
	Au < 10 ppm	Fire assay with AAS finish	0.005 - 10
	Au > 10 ppm	Fire assay with gravimetric finish	> 3
	Ag and 33 other elements	Two acid digest with ICP finish	2 - 10
Inspectorate	Ag < 200 ppm	Four acid digest with ICP finish	0.1 - 200
	Ag > 200 ppm	Fire assay with gravimetric finish	5 - 5,000

Au

Fire assay with gravimetric finish

> 3

11.3.3 QAQC

QAQC samples have been systematically included in the sample stream throughout the sampling programme, including blanks, standards, and pulp duplicates. The intended

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

protocol is based on sample number within batches of 50 samples. Sample numbers ending with 10 or 60 are Ag standards, 30 or 80 are Au standards, and 20, 40, 70, or 90 are blanks. Duplicate samples are collected at the pulp duplicate stage by the laboratory. Every sample ending with 49 or 99 is duplicated and the duplicate labelled 50 or 00 respectively. The duplicates are submitted in batches to an umpire laboratory. Pan American geologists regularly monitored the performance of standard and blank assays returned by SGS by plotting values on line graphs in Excel as soon as each batch of assays was reported by the laboratory. Whenever any of the standard results exceeded three standard deviations from the expected value, the entire batch of assays was re-submitted for re-analysis.

Blanks

Blank samples comprise full volume half core basalt. A total of 652 blank samples have been submitted with the Pan American drillhole samples which equates to a 4% insertion rate. Plots of the gold and silver assay results for the blank samples are shown in Figure 11.8. The plots in Figure 11.8 show two samples for gold and five samples for Ag to be above the detection limit. This equates to a failure rate of 0.3% for Au and 0.8% for Ag. These results show that contamination is not a major concern for these elements. The sample insertion rate should be increased to 5% from the current 4%, with the blank samples placed between suspected high grade samples in the veins.

Figure 11.8 Scatterplots of blank assay silver and gold results

September 2011

Table of ContentsPan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México
Preliminary Economic Assessment - Technical Report

Standards

A total of 662 standards have been inserted into the Pan American sampling stream, equating to a 4% insertion rate. Three different standards have been used, including ORKO-10, GBM908-13, and G308-7 and details for each standard are shown in Table 11.5. All of the standards except for GBM908-13 have been depleted and are no longer in use at the time of this report.

Table 11.5 Details of the standards used by Pan American

Standard	Ag		Au	
	Certified value (ppm)	Standard deviation	Certified value (ppm)	Standard deviation
ORKO-10	145.47	4.23	0.057	0.005
GBM908-13	151.4	8.4	n/a	n/a
G308-7	n/a	n/a	0.27	0.02

Standard Orko-10 was prepared by SGS in Durango from material obtained from stockpiles at the Property site. This standard was not certified but round robin testing consisting of five laboratories has produced expected values and standard deviations for this standard. Only 21 of these standards were analysed with drillholes BP09-355 to BP09-364. For both Ag and Au, the assay results demonstrate a bias towards higher values

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

than the expected value. Pan American commissioned SGS Peru to assess the Orko-10 (as well as Orko-9) standard material. SGS Peru concluded that the standard had unacceptably high variances, probably due to the presence of native silver. Pan American discontinued the use of Orko-10 from BP09-365 onwards.

Standard GBM908-13 and G308-7 are both certified standards obtained from Geostats (Pty) Ltd. (Geostats) and replaced Orko-10. GBM908-13 is a base metal standard which has certified values for silver, copper, and sulphur, while G308-7 is certified for gold.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México
Preliminary Economic Assessment - Technical Report

391 GBM908-13 samples and 316 G308-7 samples were submitted with the Pan American drillhole samples. The performance of these standards for silver (GBM908-13) and gold (G308-7) are presented in Figure 11.9. Although analysed standards for GBM908-13 fall within acceptable limits, a consistent bias towards over-reporting of the silver grades is present. It is also noted that the standard deviations for silver grades are very wide and do not provide a tight constraint on the precision of the analysis. G308-7 shows a very slight bias towards under-reporting of the gold grades, however, all results are within two standard deviations of the certified value which indicates a good level of accuracy.

Figure 11.9 **Graphs of the GBM908-13 and G308-7 standard results for silver and gold**

Duplicates

Pulp duplicates submitted to an umpire laboratory allow for monitoring of grade bias by laboratory. Pan American submitted a total of 321 pulp duplicates (2% of the total number of samples) returned from the primary laboratory SGS to the umpire laboratory Inspectorate in Nevada for re-analysis. No field or coarse crush duplicates have been submitted to the primary laboratory for the Pan American drillholes to assess sample grade precision. Standards were inserted into the duplicate sample stream at a rate of one in ten (10%).

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México
Preliminary Economic Assessment - Technical Report

Silver and gold results shown on the Q-Q plots given in Figure 11.10 indicate a bias towards higher silver grades obtained from the duplicate laboratory (Inspectorate) and a good correlation of gold grades with no bias in the results above the practical detection limit.

Figure 11.10 Q-Q plot comparing silver and gold assays of pulp duplicates from SGS and Inspectorate

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México
Preliminary Economic Assessment - Technical Report

11.4 Density measurements

A total of 84,105 density measurements are available in the current database for La Preciosa. Of these, 65,318 were specific gravity measurements by Orko and the remainder by Pan American. The methodology followed by Orko was to select a half drill core sample weighing between 200 g and 300 g from the sample bag, record the sample weight on an electronic scale (with a precision of 0.01 g up to 500 g), then to place the drill core in a calibrated 2,000 millilitre (ml) capacity cylinder filled with 400 ml of water, and then to measure the displaced water volume. The density value is determined by dividing the sample weight by the volume of displaced water.

MDA (2009) were concerned that the samples were not dried prior to measuring density and that no information was available to demonstrate the dryness of the samples. The greater concern was that the methodology did not account for the presence of vugs (open spaces) in the samples, which will result in an artificially high density measurement. The measurement method followed by Orko does not provide in situ bulk density, which is required for the estimation of tonnes and contained metal, because it was not undertaken on dried samples nor did it take account for any open spaces.

To assess the reliability of the density measurements for mineral resource estimation, MDA directed Orko to undertake the measurement of dry bulk density of 92 pieces of whole drill core from vein material. NQ and HQ sized drill core samples were cut perpendicular to the core axis to form cylinders with lengths between 9.4 cm and 10.6 cm. The cylinders were oven dried in a domestic toaster oven and weighed every hour until the mass of the cylinder had stabilised, with a minimum drying time of 4 hours and a maximum drying time of 8 hours. The cylinders were then weighed on a bench top scale. After a dry weight was obtained, the length and diameter of the cylinders were measured by micrometer, taking into consideration any void space, to determine the volume of the sample. The dry bulk density was then calculated by dividing the dry sample weight by the volume of the sample. Next, the sample was cut in half parallel to the core axis and a specific gravity measurement was made on the sample using the water displacement method normally followed by Orko, in order to compare the results of the dry bulk density measurements and the specific gravity measurement.

The expectation was that the specific gravity value would be higher than the bulk density value, as the vug spaces should fill with water resulting in a lower volumetric displacement of the water in the cylinder, but this turned out to not be the case. All but three of the Orko specific gravity values were higher than MDAs bulk density values on exactly the same sample. Inspection of photographs taken of 72 of the 92 samples indicated that the samples contained very minor surficial cavities (estimated at less than 1%). These results led MDA to conclude that the inaccuracy of the water displacement technique due to surficial cavities was not a major issue in the samples selected for the study. However, MDA had concerns about the precision with which each of the measurements were made, such as measuring the volume of the core by micrometer variably to the nearest 1 mm or to the nearest 0.01 mm, or by measuring the volume of displaced water to the nearest 1 ml, 5 ml, or 10 ml. MDA concluded that the Orko density values had a high variance but were not biased and were acceptable for the estimation of density as long as the high individual sample variance was considered.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México
Preliminary Economic Assessment - Technical Report

Pan American undertook density testing on approximately 252 samples to determine the method which would result in the most reliable density values by taking four different measurements using different methodologies on exactly the same rock sample. One of the four measurement techniques included data for measurement of a void index which could be used to imply bulk density. 133 samples were measured from vein and near vein silicified material and 119 from un-silicified andesite, which is the most common wall rock to the mineralisation. Oxidation state was considered by assuming oxidation is depth related and each of the two rock types were taken from shallow, middle, and deep locations to reflect the potential highly, moderately, and weakly oxidation states, with approximately 40 samples selected in each of these zones. Samples were selected from intervals weighing between 400 g to 600 g to reduce measurement error, and were mostly selected from samples that had previous Orko specific gravity measurements. Each sample was geologically logged prior to testing and the measurements were made by a well-trained metallurgical technician at the Pan American La Colorado mine metallurgical laboratory. The results of the test work indicated that the use of the Orko specific gravity data is suitable for use in mineral resource estimation as long as a factor is applied to convert to bulk density. This factor is discussed in Section 14.8.

11.5 Conclusions and recommendations

In QG's opinion, the following conclusions and recommendations regarding sample preparation, analyses, and security can be made:

- Sample handling and preparation on site follow industry standard practices. Sample security is aided by the remote nature of the site and by the permanent presence of a caretaker to ensure unwanted intrusion. Once processed, samples are driven directly from site to the sample preparation facility in Durango. No specific anti-tampering precautions are taken between site and the laboratory because the samples remain in Pan American custody during this time. There is no reason to believe that any of the drill core or results have been tampered with.
- The sample preparation and analytical laboratories used are international and certified commercial laboratories. The sample preparation and analytical methods used to determine sample grades are suitable for the mineralisation style and tenor at La Preciosa and the results are reliable for use in mineral resource estimation with due consideration of the QAQC results during mineral resource classification.
- Contamination does not appear to be a major problem during sample preparation of Pan American's drill core, but the blank samples submitted with Orko's drill core shows minor contamination in the results. There is the possibility that the blank material used by Orko was not completely un-mineralised.

The standards included in Orko's sample stream were problematic because they were not certified, record keeping is reported to have been inadequate and therefore the identity of the standards was not always certain, the standard deviation of some of the standards are unusually high, and some of the accepted values are very similar to other standards. Therefore it is unclear whether any observed inaccuracies are due to inconsistencies in the standard itself, mislabelling of the standard during sample submission, or errors in the assay procedure. Standards included in Pan American's sample stream show all results are accurate within two standard deviations of the certified value for both silver and gold, with a slightly high silver bias and a slightly low gold bias.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

- Certified standards at low, medium, high, and cut-off grades with relatively narrow standard deviation ranges, for both silver and gold, should be purchased. The certified values of the various standards should not overlap in grade value to eliminate the possibility that mislabelled standards are the cause of any failed assay results. The certified standards should be sourced from an international certified standard provider or preferably prepared from material obtained from site and prepared by an accredited laboratory for full independent certification. The certified standards should be inserted in the sample stream at a submission frequency of one for every 20 geological samples.
- Duplicate samples from Orko's drilling campaigns show good precision and no bias when the comparison is made between the original and duplicate sample assays prepared and analysed by the same laboratory. When duplicate samples were sent to check laboratories however, the results were mixed and sometimes conflicting. In some cases there was no way to assess which laboratory is more accurate as no standard results for some batches are available. Duplicate samples submitted by Pan American to the check laboratory show that the original sample grades have a low silver bias and no bias is noted in gold.
- Duplicate samples comprising coarse reject samples as well as pulps should be submitted to the primary laboratory to monitor sample precision at the primary laboratory, at a submission frequency of one for every 20 geological samples. Duplicate samples should be focussed on sample intervals in the vein material. Whenever duplicate sample campaigns are undertaken, the check laboratory should use the same analytical method as the primary laboratory.
- During check sampling campaigns, both standards and blanks should be submitted to assess for sample contamination and sample accuracy at the check laboratory.
- All QAQC data should be assessed as assay results are received and any required corrective action should be undertaken immediately.
- Despite the lower performance of some of the QAQC data, it is QG's opinion that the sample data is reliable for use in mineral resource estimation with due consideration of the QAQC results during mineral resource classification. In future, the reliability of sample grades can be demonstrated by favourable results of QAQC samples submitted with infill drillhole samples as the Project advances.
- Bulk density measurements should continue to be made from spatially and lithologically representative areas of the mineral resource as drilling continues.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

12 Data verification

12.1 Data verification by MDA and Pan American

MDA (2009) assessed a re-assay campaign of coarse rejects undertaken by Orko and instigated a re-assaying programme of pulp samples and the results of this assessment are discussed in Section 11.2.3. During classification of the mineral resource estimate disclosed in 2009, MDA attributed as negative factors the grade biases noted between the original and re-assayed grade values and the lack of available Orko QC data to demonstrate the quality of sample data.

To eliminate any concerns about the quality of Orko data, Pan American undertook a specific testing programme of original data by re-assaying drillhole samples and by comparing recent Pan American drillhole sample grades with earlier Orko sample grades, which also showed grade biases.

While the check programmes were not entirely adequately undertaken and some of the results are inconclusive, it is QG's opinion that the check assaying performed by Pan American has not raised any major concerns with the quality of previous drillhole sample data and reinforces the suitability of the Orko data for inclusion into mineral resource estimates classified as either Inferred or Indicated. In future, the reliability of sample grades can be demonstrated by favourable results of QAQC samples submitted with infill drillhole samples as the Project advances.

12.2 Data verification by the current qualified persons

12.2.1 Site visit

Mr. Snider visited the site on 9 June 2011, accompanied by Hernán Dorado Smith, Senior Planning Engineer of Pan American. Mr. Snider reviewed the site and select process plant and tailings locations.

Mr. Finch and Mr. Stewart visited the site on 5 July 2011. Mr. Finch reviewed the potential pit locations, the portal and the dump locations, as well as the general infrastructure and access to the site.

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

Mr. Stewart reviewed representative drill core intersections of the veins and surrounding host rock located at the core storage facility on the Property site, confirmed the collar coordinates of selected drillholes, visited outcrops of the Martha, Gloria, Abundancia, and Transversal veins, reviewed paper and digital geological interpretations, and reviewed the geological database. At the time of inspection, no drill rigs were operating and no drill core handling processes were observed. Core handling procedures were discussed with Mr. Sergio Morfín, Exploration Manager México, including core mark-up, sample recovery and geotechnical logging, geological logging, sample delineation, sample cutting, insertion of QC samples, and sample dispatch.

The reviewed drill core intersections were chosen to represent the various structures and veins, different generations of drilling, and important high grade intersections. No discrepancies were noted between the information reviewed by Mr. Stewart and the data and information that has been provided by Pan American.

Because a current personal inspection has been conducted by other qualified persons responsible for the preparation of this technical report, and no additional beneficial

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

information would have been derived from a site visit at this stage of the Project, Mr. Hawthorn and Mr. Drielick did not conduct a site visit. Mr. Hawthorn and Mr. Drielick reviewed the available data and consider that it is adequate for the purposes of this preliminary economic assessment.

12.2.2 Data reviews

Downhole surveys

A review of the down hole survey data indicates that a number of down hole surveys are incorrect, caused either by data transcription errors or by errors in the survey measurement. Additionally, no down hole surveys were taken at the collar of each drillhole, and the planned bearing and dip was entered in the database as the actual orientation at the collar. This practice has resulted in greater differences between the bearing and dip at the collar and the first actual down hole survey than is present between consecutive down hole surveys further down the hole. The reason for this discrepancy is that drillholes are rarely collared with exactly the same bearing and dip as is planned. Since nearly all of the drillhole collars are well preserved with a standpipe at the collar, it is recommended that a licensed surveyor take a bearing and dip measurement of all drillhole collars. As well, the down hole survey database should be reviewed for unrealistic differences between consecutive down hole surveys and checked against the values recorded on the driller's log. Any unresolved differences should be noted and a correction applied to the survey to ensure that the location of the drillhole trace is accurately plotted for geological interpretation and mineral resource estimation.

Drillhole collar coordinates

14 collar coordinates were independently confirmed by QG using a hand-held GPS. No discrepancies beyond the accuracy of the handheld GPS were noted between the GPS reading and the values in the database.

Assay database

Original assay certificates from SGS Laboratories in Durango, México and from Inspectorate America Corporation in Sparks, Nevada were emailed directly to QG for comparison against the values in the database. 441 assays from Pan American's drilling and 3,188 assays from Orko's drilling were reviewed. 44 errors were noted in Pan American's assay database, and 41 of these are related to a single assay batch which appears to have been re-assayed. It is not clear whether the values in the database relate to the final, accepted assay or whether the wrong certificate was provided. Two of the three remaining errors relate to inconsistent treatment of below detection limit assays, which has no effect on the estimation of mineral resources, and one assay was entered in error as the threshold of the AAS result rather than the fire assay result. Nine errors were noted in Orko's assay database, seven of which require follow up as it appears that repeat assay values have been entered in the database as the average of the two assays values, rather than the first assay value, as is best practice.

QG recommends that Pan American review all assays in the database for accuracy and ensure consistent treatment of below detection limit assays and repeat assay values. Standard practice is to store all raw assays in the database and to create columns which contain the final assay values for use in mineral resource estimates. Standard practice for entering assays below detection limit assays is to enter half the detection limit of the analytical machine. Standard practice for entering assays with repeat values is to enter

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

the first assay value, unless an error has been identified with the first assay value, in which case best practice would be to use the second assay value.

Any assay certificates that have been superseded by a re-assay of the entire batch, such as in the case of failed QAQC results, should be identified in the database in order to facilitate data reviews.

Data should be stored in an industry standard database and data should be digitally captured using electronic geological logging and assay transfer software to ensure timely and accurate collection of geological data. This will provide robustness in the data capture process and security in the database.

QAQC reviews

Snowden were retained by Pan American to review all available QAQC data and to compile the information in a master database with the corresponding geological log data and with the three dimensional coordinate information, in order to assess the spatial distribution of the QAQC data and results. The results of Snowden's assessment (Snowden, 2011) are documented in Section 11 of this technical report.

12.3 Data adequacy

It is the opinion of the qualified persons responsible for the preparation of this report that the data used to support the conclusions presented in this technical report is adequate for the purposes of this preliminary economic assessment.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

13 Mineral processing and metallurgical testing

Luismin initiated the first metallurgical test work on La Preciosa Project samples in 1988 in anticipation of processing mined material at their Avino mine located 20 km to the northeast of the Property. No other test work was undertaken until the modern series of testing from 2007 to 2010. Between 2007 and 2009, testing took place at the Process Research Associates (PRA, now Inspectorate) laboratory in Richmond, BC, and at Westcoast Mineral Testing Inc. (WMT) of North Vancouver, BC. Following the joint venture agreement between Orko and Pan American in 2009, the metallurgical composites were shipped to the SGS metallurgical laboratory in Durango, México, where they were used to prepare a new master composite that was used in the first of four programmes. Subsequently, a second master composite and variability composites were prepared for testing at SGS.

13.1 Historical testing

Whiting (2008) reports that historical Luismin reports have some brief descriptions of a preliminary metallurgical testing and bulk processing of mineralised rock extracted from the Abundancia and La Gloria veins during the slashing of the underground workings. Most of this testing was designed to determine the amenability of the material to serve as process feed to concentration in the Avino mill. In 1988, Comisión de Fomento Minero completed three cyanidation bottle roll tests on 9 kilograms (kg) samples ground to ¾, ½, and 3/8 inch size, as well as a finer 65% passing through a -200 mesh. A cyanide concentration of 0.2% NaCN, with incorporated lime to maintain a pH at 11, yielded the preliminary results shown in Table 13.1.

Table 13.1 Metallurgy test results by Comision de Fomento Minero

Sample Size	Heads		Tails		Recovery	
	Au ppm	Heads Ag ppm	Tails Au ppm	Tails Ag ppm	% of Au	Recovery % of Ag
-3/4	0.45	254	0.32	240	28.9	5.5
-1/2	0.45	254	0.26	233	42.2	8.3
-3/8	0.45	254	0.20	210	55.5	17.3
65% -200	0.45	254	0.12	41	73.3	83.9

13.2 Testing from 2007 and 2009

Bench scale testing during this period investigated the response to both flotation and agitation cyanidation.

13.2.1 Stage 1 flotation and agitation cyanidation tests

In December 2007, five 10 kg composites, all as nominally 6 mesh drill core assay coarse rejects were shipped to WMT. Summary details of the five composites are shown in Table 13.2. Portions of each of these five composites were used to prepare a single master composite grading 0.4 ppm Au and 300 ppm Ag. This master composite was

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

subjected to a single flotation test by WMT plus three agitation cyanidation tests by PRA.

The remaining portions of the original five composites were sent in mid-2009 to Pan American in Durango, México, where they provided material for the first of four testing programmes undertaken by Pan American.

Table 13.2 Details of the five 10 kg Orko metallurgical composites

Composite name	No. of samples	Ag	Au	Pb	Zn	Cu
		ppm	ppb	ppm	ppm	ppm
Veta La Gloria	26	310	328	1887	2364	108
Veta Abundancia	18	250	379	3114	3694	125
Veta Martha	40	261	291	1092	2815	130
Veta Transversal	13	236	147	2610	2827	59
Veta Luz Elena	19	445	510	2220	4869	206

WMT flotation test W-07-37

A staged rougher-only flotation test (No. W-07-37) by WMT reported modest recoveries of both silver and gold (73.5% and 44.0%, respectively), with very limited potential to increase recoveries by any change in process variables. The results of the test work are shown in Table 13.3.

The following test conditions were used:

- Grind - 42% - 200 mesh (P80 = 200 microns).
- Pulp density of 20%.
- Frother - DF 250.

- Collector initially 9 ppm of Cytec 3418A then 30 ppm potassium amyl xanthate (PAX).
- pH natural at 8.8.
- Copper sulphate was added at the final stage of flotation, but it did not result in any flotation increment.
- Flotation to completion, requiring about six minutes.

The overall ratio of concentration was high with only 2.8% of the feed weight reporting to the overall rougher concentrate. The concentrate weight could be significantly decreased by cleaning, since the first rougher concentrate contained only about 35% sulphides, mainly as pyrite, with about 10% as sphalerite and 5% as galena.

Given the high ratio of concentration, if any future testing is undertaken, Cytec selective collector 3418A should be eliminated, retaining only the very strong and non-selective PAX as a bulk flotation collector.

Compared to the initial cyanidation results, the recoveries of silver and gold did not encourage the use of flotation for the global deposit. The use of a single master composite was a cost effective method to review the global deposit, but subsequent cyanidation testing reported that the gold in the Martha sulphide has a different response than after oxidation.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 13.3 **Rougher only flotation test results**

Product	Weight %	Overall flotation				
		Ag ppm	Au ppm	Pb%	Fe%	Zn%
1st rougher concentrate	1.4	14,360	8.26	4.41	9.4	6.63
2nd rougher concentrate	1.4	1,905	3.20	2.58	9.3	4.74
Overall rougher concentrate	2.8	8,001	5.68	3.48	9.3	5.67
Rougher tailing	97.2	84	0.21	0.21	2.7	0.26
Feed calculated	100.0	308	0.37	0.30	2.9	0.41
Feed from composite grades		300	0.33	0.21	2.9	0.33

Product	Distribution %				
	Ag%	Au%	Pb%	Fe%	Zn%
1st rougher concentrate	64.6	31.3	20.2	4.5	22.4
2nd rougher concentrate	8.9	12.7	12.3	4.6	16.7
Overall rougher concentrate	73.5	44.0	32.5	9.1	39.1
Rougher tailing	26.5	56.0	67.5	90.9	60.9
Feed	100.0	100.0	100.0	100.0	100.0

The tailing screen assay data, shown in Table 13.4, indicates a distribution of silver and gold for the flotation tailings product.

Table 13.4 **Rougher tailing screen assay data**

Mesh	Weight %	Ag ppm	Au ppm
	18.4	110	0.16
65	12.9	89	0.16
100	15.7	74	0.17
150	10.1	64	0.17
200	12.9	69	0.16
325	30.0	84	0.32
Weighted average	100.0	84	0.21
By direct assay		84	0.24

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

PRA cyanidation tests Orko C1 to C3

Because of the low recovery results in the flotation test, the study shifted to the investigation of agitation cyanidation. The first cyanidation test (Orko C1) demonstrated the amenability of both gold and silver with cyanidation and two additional tests were performed to investigate indications of grind and cyanide concentration sensitivities. The three 96 hour kinetic tests, all at pH 10.0-10.5 and a pulp density of 40%, were undertaken by PRA and the results are summarised in Table 13.5.

Table 13.5 Orko cyanidation tests C1 to C3 results

Test	NaCN (g/l)	Grind (P80 microns)	Ag head grade (ppm)	Ag extraction (%)	Au head grade (ppm)	Au extraction (%)	NaCN consumption (kg/t)
Orko C1	2	227	335	75.8	0.44	81.6	2.14
Orko C2	1	80	300	64.9	0.49	78.5	0.72
Orko C3	4	97	327	89.1	0.85	88.0	2.56

This test series determined the following:

- Silver recovery is sensitive to both grind and cyanide concentration.
- Gold extraction does not appear to be particularly sensitive to grind but possibly sensitive to cyanide concentration.
- A retention time of 72 hours appears to reach a point of diminishing returns.
- Although test C3 reported the highest silver extraction, the extent to which grind and cyanide concentration each contributed to those results is uncertain given both parameters were varied. Future testing should investigate cyanide concentrations surrounding 2 g/l and at finer grinds.

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

- These tests suggest that silver extraction will be low unless the cyanide concentration is sufficiently high to incur cyanide consumption greater than 2 kg/t. That was not confirmed in subsequent testing at SGS in Durango.
- It would appear that the optimum silver recovery may require a grind that is at least as fine at P80 = 100 microns.
- There were no significantly elevated concentrations of any of the normal cyanicides in the pregnant leached solution (PLS), however, there could be potential to reduce cyanide consumption by increasing the pH.

The screen assay on the leached residue for test C3, shown Table 13.6, indicates that gold extraction is not grind sensitive but silver extraction could potentially benefit from finer grinding. This characteristic was later demonstrated by almost all of the composites for which this type of data was provided.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 13.6 **Screen assays of Orko test C3 leached residue**

Tyler mesh size fraction	Weight (%)	Au ppm	Ag ppm
+105	16.3	0.11	63.2
-105+74	15.6	0.10	39.7
-74+53	13.1	0.12	35.4
-53+37	10.3	0.12	35.6
-37	44.7	0.09	24.0
Calculated	100.0	0.10	35.5

The kinetic curve for test C3 suggests that three days of agitation leaching is required to achieve a point of diminishing returns. In future testing, four days of leaching is justifiable to increase silver extractions providing improved economic returns.

At this stage of the testing it appeared that agitation cyanidation is superior to flotation.

13.2.2 Stage 2 bottle roll leaching tests

In mid-2008, 12 composites from diamond drill core sample assay coarse rejects for agitation leaching testing were prepared for bottle roll leaching tests at PRA. Details of the 12 composites are shown in Table 13.7. The comparative assay data shows acceptable repeatability of the composite grades using several assay procedures.

These composites represented the major mineralised zones known at the time and included both oxide and sulphide composites from the Martha zone. Since the drill core geological logs and an examination of the drill core identified both oxide and sulphide mineralisation, it was useful to determine whether sulphide encapsulation of the gold and silver minerals has any role in cyanide leaching.

The Stage 2 tests were performed with the following details:

- Nominal P80 = 80 microns.

Edgar Filing: PAN AMERICAN SILVER CORP - Form 6-K

- NaCN concentration = 1 g/l.
- pH = 10.5.
- Pulp density of 40% solids.
- Leaching time: 72 hours for the first six composites, then 96 hours for the last six.
- All as kinetic tests.
- All tests were run in triplicate.
- Every third test (one on each composite) included tailing screen assaying for gold and silver.

The following findings were reported from the test work:

- Low extraction of silver, averaging 76%, with 5% difference in silver extraction between the oxide and sulphide composites with the oxides yielding lower silver extraction than the sulphide composites.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

- Gold extraction from the three Martha sulphide composites of 45.1%, with a large variance between the 80.9% average results in the oxides and 45.1% average results in the sulphides.
- A somewhat elevated cyanide consumption ranging from 0.9 to 1.9 kg/t, averaging 1.4 kg/t.

Although the global gold feed grade is less than 0.3 ppm, it does provide an increment of economic recovery, so the impact of gold extraction cannot be ignored.

The following can be concluded for the test series:

- Many of the tests did not completely leach at either 72 or 96 hours. This is potentially attributable to a low (1 g/l) cyanide concentration, and not necessarily a result of insufficient leaching time as the combined effects of cyanide concentration and retention time is not defined.
- The gold is not grind sensitive, although it did appear to leach slowly.
- Based upon the previous Orko tests the cyanide concentration may need to be increased to a minimum of 2 g/l in the next test series.
- In the context of gold, the Martha sulphides reported significantly lower extractions than did the oxide composites.

The summarised results are shown in Table 13.8.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 13.7 Stage 2 agitation leaching composite summary data

PRA sample number	Composite description	Number of samples	Mean grade of individual samples Ag ppm	Composite grade		Composite screen assay grade		Back calculated grade from met testing	
				Ag ppm	Au ppm	Ag ppm	Au ppm	Ag ppm	Au ppm
1	Abundancia low grade composite	28	56	51	0.12	52	0.21	60	0.15
2	Abundancia medium grade composite	23	150	144	0.29	140	0.35	154	0.29
3	Abundancia high grade composite	25	375	367	0.36	371	0.41	364	0.50
4	Gloria low grade composite	16	49	52	0.12	54	0.11	57	0.14
5	Gloria medium grade composite	24	152	161	0.23	153	0.22	172	0.30
6	Gloria high grade composite	20	380	395	0.34	375	0.30	400	0.34
8A	Martha sulphide composite 1	53	130	126	0.24	124	0.33	125	0.29
8B	Martha sulphide composite 2	44	231	182	0.45	212	0.44	197	0.49
9	Martha sulphide composite 3	33	316	275	0.38	285	0.39	280	0.47
10	Martha mix composite 1	29	43	40	0.11	43	0.14	41	0.18
11	Martha mix composite 2	29	218	201	0.26	234	0.29	217	0.36
12	Martha oxide composite	45	195	195	0.34	196	0.35	195	0.41

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

Table 13.8 Stage 2 agitation leaching testwork results

Sample number	Description	P80 size (microns)	Extraction		Residue		Consumption (kg/t)	
			Au (%)	Ag (%)	Au (ppm)	Ag (ppm)	NaCN	Lime
1	Abundancia - low grade	89	77.0	67.1	0.04	20	0.9	1.1
2	Abundancia medium grade	88	83.9	70.9	0.05	45	1.1	0.7
3	Abundancia high grade	79	81.0	80.1	0.09	73	0.8	0.9
4	Gloria low grade	52	77.9	72.3	0.03	16	1.0	1.3
5	Gloria medium grade	85	85.2	75.3	0.04	43	1.1	0.9
6	Gloria high grade	80	85.2	67.0	0.05	132	1.1	0.8
8A	Martha sulphide 1	52	39.7	83.5	0.18	20	1.9	1.1
8B	Martha sulphide 2	78	51.7	79.6	0.24	42	1.6	1.0
9	Martha sulphide 3	77	43.9	76.2	0.27	67	1.7	1.0
10	Martha mixed	78	72.7	81.3	0.05	8	1.5	1.1
11	Martha mixed	82	80.0	83.9	0.07	38	1.9	1.0
12	Martha oxide	82	85.4	75.6	0.06	49	1.8	1.0
Average of all			72.0	76.1	0.10	46	1.4	1.0
Average oxide			77	80.9	0.05	47	1.3	1.0
Average sulphide			45.1	79.8	0.23	43	1.7	1.1

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

13.2.3 Stage 3 cyanidation and flotation tests

PRA cyanidation tests C37 to C42

On reviewing the Stage 2 test results, the following important processing characteristics became relevant to subsequent cyanidation testing:

- A grind of P80 = 80 microns appeared to be more or less optimum at current silver prices.
- The cyanide concentration should be increased. Although 2 g/l was believed to be adequate, 4 g/l was initially used to assure technical success.
- The test time needs to be 96 hours to reasonably determine optimum leach retention time.

Cyanidation testing (PRA tests C37 to C42) was performed on six composites, which were made from re-compositing the Stage 2 composites in order to achieve silver grades of 200 ppm. Details of the composites are shown in Table 13.9. The composites were all subjected to tailing screen assaying and ICP analysis of the pregnant leaching solution.

The test conditions were as follows:

- Target grind P80 = 90 microns.
- Pulp density = 40% solids.
- Retention time = 96 hours.

- Cyanide concentration = 4 g/l.
- pH = 10.5
- Test method by kinetic bottle roll cyanidation.
- Tailing screen analysis was reported for gold and silver for every test.

The following observations are noteworthy:

- pH = 10.5
- The silver extractions were in the narrow range of 88.1% to 92.0%, averaging 90.1%, suggesting that the silver metallurgy is similar in both oxide and sulphide material.
- The consumption of cyanide was anomalously high at a typical 10 kg/t. This is unexplained by the analysis of the pregnant leaching solution and raises serious questions about the reliability of the results.
- The kinetic curves consistently show that silver leaching has reached completion in 48 hours, but gold is still leaching at 96 hours. This is also an anomalous feature. Irrespective, it appears both silver and gold extractions increased substantially in this Stage 3 testing compared to the results of the Stage 2 testing.
- Silver recoveries increased from averages of 77.9%, 82.6%, and 75.6% in the Stage 2 tests to 87.8%, 92.0%, and 92.0% for Stage 3 Martha sulphide, mixed, and oxide tests, respectively, under similar parameters. Gold recoveries increased from averages of 47.8%, 76.4%, and 85.4% in Stage 2 to 63.7%, 81.8%, and 89.6% for Stage 3 Martha sulphide, mixed, and oxide, respectively.

September 2011

Table of Contents

Pan American Silver Corp. and Orko Silver Corp. La Preciosa Silver Property, Durango, México

Preliminary Economic Assessment - Technical Report

under similar conditions. These results have to be viewed with caution given the anomalously high and unexplained cyanide consumptions in the Stage 3 tests.

- As had been reported in the Stage 2 testing, gold recovery is significantly lower in the Martha sulphide composite, although not nearly to the degree experienced in the Stage 2 work. The 60.2% gold extraction in the Orko # 3 (Martha) composite in this Stage 3 testing was significantly lower than the 88% result achieved in the Stage 1 test series.

A summary of the results from PRA cyanidation tests (C37 to 42) is shown in Table 13.10.

Table 13.9 Details of composites used in PRA cyanidation tests C37 to C47

Sample description	Zone	Calculated Head Grades		Composite preparation
		Ag (ppm)	Au (ppm)	
Comp 2A	Abundancia	196	0.44	400 g of Stage 2 2 and 100 g of Stage 2 3
Comp 5A	Gloria	213	0.51	400 g of Stage 2 5 and 100 g of Stage 2 6
Comp 8B	Martha sulphide composite 2	217	0.52	original Stage 2 composite
Comp 11	Martha mix composite 2	231	0.31	original Stage 2 composite
Comp 12	Martha oxide composite	225	0.50	original Stage 2 composite
Orko 3	Veta Martha	269	0.41	original Veta Martha composite

Table 13.10 PRA cyanidation test C37 to C42 results

Test No	Sample ID	P80 size (microns)	Extraction		Au (ppm)	Residue		Consumption	
			Au (%)	Ag (%)		Ag (ppm)	NaCN (kg/t)	Lime (kg/t)	
C37	2A	90	88.1	88.1	0.05	23	10.09	1.03	
C38	5A	91	91.0	91.3	0.05	18	10.98	0.68	
C39	8B	96	63.7	87.8	0.19	26	10.50	0.73	
C40	11	90	81.8	92.0	0.06				